




*Pacific Gas and
Electric Company®*















PSOS-0451



SYSTEM INSPECTIONS ET GROUND CONTRACTOR PROCESS

2023 Program Year Version 1.0

Welcome to 2023 System Inspection Training

	Mobile Iron (Security)		Construct App <i>Use to view pending EC/LC Notifications</i>
	F5 (Security): <i>Make sure slider is turned on</i>		Maps+ <i>Review, Create, and Update Alerts</i>
	Apps@Work <i>Use to download PG&E Applications</i>		Smart Mobile Workforce <i>View System Inspections document offline</i>
	Outlook <i>Use to access PG&E e-mail</i>		Google Earth <i>Satellite and Street View</i>
	Teams <i>Use to access Systems Inspections channels</i>		Issue Tracker (via SIHelpdesk channel in TEAMS) <i>Used to submit issues to Helpdesk team</i>
	Inspect App <i>Core Inspection Application</i>		For Employee us only: LiveSafe (Daily Health Check-in) <i>Tap continue, load other apps</i>
	Web at work		SharePoint



Safety and Security Orientation



Earthquake

- Drop
- Cover
- Hold



Fire

- Exits, escape routes, evacuation plan
- [Compliant fire extinguisher](#)



Medical Emergency

- First aid/CPR
- 911/share location
- AED



Security

- Active shooter—get out, hide out, take out*
- Use badge—don't tailgate
- Lock computer
- Report Phishing emails
- Protect data privacy



Ergonomics

- 30/30
- [Proper ergo](#)
- RSI Guard



COVID-19

- Handwashing/masking
- CAL-OSHA regulations, local county health orders
- [Visit COVID-19 website](#)
- HR Helpline
415-973-4357



Emergency Planning

Update [emergency contacts](#) and [personal emergency preparedness plan](#)



Psychological Safety

- Care for each other
- Look out for one another
- Create a safe space for all
- Welcome new ideas from everyone
- Practice self-care



On the road, off the phone.



[Follow the Keys to Life](#)













EVERYONE AND EVERYTHING IS ALWAYS SAFE

Delivering for our hometowns. Serving our planet. Leading with love.



KEYS TO LIFE

-  1 Conduct pre-job safety briefings prior to performing work activities.
-  2 Follow safe driving principles and equipment operating procedures.
-  3 Use personal protective equipment (PPE) for the task being performed.
-  4 Follow electrical safety testing and grounding rules.
-  5 Follow clearance and energy lockout/tagout rules.
-  6 Follow confined space rules.
-  7 Follow suspended load rules.
-  8 Follow safety at heights rules.
-  9 Follow excavation procedures.
-  10 Follow hazardous environment procedures.

Getting Started



Get Acquainted
Record Attendance



Ground Rules

What is expected?

- Ensure safety first
- Silence cell phones
- Be prepared and ready to work
- Return from breaks on time
- Eliminate distractions
- Act respectfully
- Act professionally
- Choose a positive attitude
- Avoid profanity
- Speak up if you have questions
- If you are listening to this presentation while driving, you must pull over and park in a safe and legal location



Course Objectives

When you complete this course, you will be able to:

- Understand the procedures to perform a Transmission Line Inspection
- Understand when and how to document Compelling Abnormal Conditions and Third-Party Infractions
- Understand your tasks
 - ✓ Start of your shift
 - ✓ While Performing Detailed Inspections
 - ✓ End of your shift
- Learn when and how to
 - ✓ Use Job Aids
 - ✓ Escalate safety conditions
- Software Demo (SMW and Issue Tracker)

Class Agenda

Training begins

Break(s)

Training ends





Electric Transmission Preventative Maintenance (ETPM) Overview

ETPM Manual

Your primary reference for transmission overhead inspections is the ETPM (TD-1001M) and the associated job aids. Found in the SMW Application, the ETPM is stored in the library within the Transmission folder.

This Manual covers preventive maintenance for overhead and underground Electric Transmission Facilities. These facilities must be inspected in accordance with this Manual.

Note: TD-8123P-103, *Electric Transmission Line Guidance for Setting Priority Codes* supersedes sections 2.3.5.1 through 2.3.5.4, including Tables 3 and 4.






Electric Transmission Preventive Maintenance Manual

TD-1001M

August 31, 2020

Revision: 05


Transmission Inspections – Program Elements

	Inspection	Description: An Inspection is any preventative maintenance activities that include detailed visual observations of individual components, structures and equipment, operational readings; and component testing (i.e., hammer test, etc.) to identify abnormalities or circumstances that will negatively impact safety, reliability, or asset life.
	Compelling Abnormal Condition	Description: A Compelling Abnormal Condition is defined as being any Electric Transmission structure, conductors, equipment, components, vegetation and third-party condition that cause a safety or fire ignition risk that may adversely impact public safety and/or service reliability or asset life.
	Duty to Act	<p>Description: While executing Transmission Inspections, when you observe obvious structural conditions on PG&E or Third-Party assets, whether this location is part of your assigned work, you have a Duty to Act to report the condition.</p> <ul style="list-style-type: none">• For PG&E facilities, report conditions using the LC Notification form• For Third-Party facilities, report conditions using the LC Notification form

Transmission Inspection Program

PG&E’s Transmission Inspections Program is a preventative maintenance program designed to perform Detailed Inspections on PG&E’s Transmission facilities.


The Program uses a risk-based model that prioritizes enhanced inspection cycles based upon California’s High-Fire Threat District (HFTD) maps and other criteria.



Overview

Detailed Inspection has these major requirements:


- Achieve an un-obstructed 360-degree view of the structure
- Achieve an un-obstructed view of the Conductors from structure to mid-span / termination point
- Assess field conditions
 - Identify and record compelling abnormal conditions and third-party infractions that negatively impact safety or reliability
 - Perform Minor Work if authorized to do so
 - Take photos of PG&E assets and compelling field conditions
 - Complete a Detailed Inspection Checklist to document your inspection results, observations, findings, photos.
 - Validate pending LC notifications



Overview

Use the Inspect App to:

1. Record Checklist
2. Document Compelling Abnormal Conditions and Third-Party infractions
3. Review and Update pending LC notifications



NOTE: When a compelling abnormal condition is not listed on the Inspection Checklist, complete the Inspection Checklist according to normal processes and separately create an LC for the unique condition that was not identified in the Inspection Checklist.

Roles and Responsibilities

Contract Inspector

- Works safely and adheres to safety protocols
- Performs inspections of Transmission Facilities
- Documents the result of each inspection using the Inspect App
- Submits corrective work (LC) notifications using the Inspect App (as needed)
- Notifies PG&E Lead when work assignments need to be adjusted
- Validate pending LC Notifications



Roles and Responsibilities (continued)

PG&E Lead, Inspection Review Specialist (IRS)

- Provides guidance and manages escalations
- Ensures contractors are working safely
- Facilitate field training and classroom training for onboarding
- Acts as a primary contact for:
 - Safety Concerns
 - Access or Customer Issues
 - Emergency Priority-**A** Notifications
 - Technology Issues
 - Raptor Kill
 - Work Escalations
 - Mis-matched Operating Numbers



Roles and Responsibilities (continued)

PG&E Construction Manager (CM)

- Work and resource planning
- Manages and schedules work assignments via Engage work assignment tool
- Work and resource coordinator for internal Supervisors and Contractors
- Coordinate with Vegetation and Aerial departments

Contractor General Foreman (GF)

- Acts as the primary contact for Safety Incidents
- Provides oversight and guidance for Contractors
- Attendance and Scheduling



Hand-written Records

When using paper forms, the following is required:

- Use non-erasable black or blue ink pen.
- Do not erase or use white out.
 - If an error is made, white out is not acceptable. Instead, draw a line through the original information, write your initials and the date, and then write the correct information. Do not black it out completely.
- Paper records must be retained.
- Follow guidelines for turning in physical records.



Knowledge Check

Let's review:

What is a compelling abnormal condition?

- A. Yard sale sign attached to a pole
- B. Locked gates, barking dog, customer refusal
- C. Any Electric Transmission structure, conductors, equipment, components, vegetation and third-party condition that cause a safety or fire ignition risk that may adversely impact public safety and/or service reliability or asset life.

Knowledge Check

Let's review:

What is a compelling abnormal condition?


- A. Yard sale sign attached to a pole
- B. Locked gates, barking dog, customer refusal
- C. Any Electric Transmission structure, conductors, equipment, components, vegetation and third-party condition that cause a safety or fire ignition risk that may adversely impact public safety and/or service reliability or asset life.

Inspection Approach

The proper method of inspection is determined by the type of structure and the type of inspection (e.g., detailed ground, climbing, aerial, infrared).

Inspectors perform the inspections by reviewing each asset (e.g., structure, conductor, foundation, hardware, insulator).

PGE Transmission System consists of Steel Towers, Steel Lattice Towers, Steel Poles, Multiple Poles, Light Duty Steel Pole, Fiberglass, and Wood Poles.





Multi-Pole w Shared Crossarm

Ground Inspection Checklist

Multi-Pole Structures with Shared Crossarm Supporting Conductors

1. Multi-Pole Structures have 2 or 3 poles with a shared crossarm supporting conductors.
2. Multi-Pole Structures may be referred to as H-Frame structures.
3. This guidance supports all multi-pole structures with a shared crossarm supporting conductors.

Requirement: Inspect all attachments that are associated with the structure being inspected.

Scenario # 1



Scenario # 2




Ground Inspection Checklist

Multi-Pole Structures with Shared Crossarm Supporting Conductors

Scenario #1

1. Inspect the asset with the Orange Halo. This includes the structure (pole) and all attachments.
2. Inspect the shared crossarm because it is attached to the pole being inspected.
3. Inspect all insulators and other attachments including hardware, framing, signage, etc.
4. Inspect all attached conductors.
5. Inspect all foundation, guy/anchors, vegetation, etc.
6. Follow ETPM, Job Aids, Training Material, and Checklist requirements.
7. Photos:
 - ☐ Take photos showing all multi-pole structures
 - ☐ Take photos showing all attachments including the whole shared-crossarm
 - ☐ Take photos showing all strings (hot/cold ends) insulators per the checklist requirements
 - ☐ Take photos showing all lines




Ground Inspection Checklist

Multi-Pole Structures with Shared Crossarm Supporting Conductors

Scenario #2

1. Inspect the asset with the Orange Halo. This includes the structure (pole) and all attachments.
2. Inspect the shared crossarm because it is attached to the pole being inspected.
3. Inspect all insulators and other attachments including hardware, framing, signage, etc.
4. Inspect all attached conductors.
5. Inspect all foundation, guy/anchors, vegetation, etc.
6. Follow ETPM, Job Aids, Training Material, and Checklist requirements.
7. Photos:
 - ☐ Take photos showing all multi-pole structures
 - ☐ Take photos showing all attachments including the whole shared-crossarm
 - ☐ Take photos showing all strings (hot/cold ends) insulators per the checklist requirements
 - ☐ Take photos showing all lines





Daily Workflow

Start of Shift

- Ensure good Cell / Wi-Fi service
- Check Emails
- Check Teams & SMW
- Check Inspect
 - Refresh map
 - Touch ‘Work’ to view Assignments, select MP, Start Checklist to view haloed assets
- Sync Work
- Ensure battery packs are fully charged
- Ensure proper tools and equipment are on the truck
- Follow the Safety Action Plan

Safety Action Plan

- Identify inspection locations to plan travel route
- Check weather reports
- Check wildfire risks
- Confirm route is safe to drive/walk/hike
- Check Enterprise Alerts
- Identify types of terrain
- Travel to first job site & submit Safety Tailboard

Perform Inspection

Identify Safety Risks

- Confirm slope less than 40 degrees
- Use Maps+ (If needed)
 - Create Field Intel with new access information
 - Create Field Intel with bad dog information
- Assess Cannot Get In (CGI) conditions
 - Create CGI Notification
- Assess Emergency conditions
 - Create Priority-A Notification
- Review the open LC map layer
 - Locate, Review, & Understand existing LCs
- Assess mapping discrepancies
- Request to add Halo via email, move to next structure

Before starting Checklist

- Perform Minor Work (Troublemakers/Towermen only)
- Always Measure/Record Guy Tension (Towermen only)
- If needed, Adjust/Record Guy Tension (Towermen only)
- Perform Mechanical testing (Troublemakers only)
- Perform Visual Inspection
- Take all photos for all forms

Start Inspection Checklist

- Use the Inspection Checklist as a guide to ensure your visual inspection is accurate and complete
- Attach field photos
- Update Pending LCs

Submit Inspection Checklist

After Submitting Checklist

- Perform Resubmission (if needed)
- Send Email for All Halo issues (if needed)

Throughout the Day

- Travel to cell service, as needed
 - Call IRS, Lead, or Supervisor for Emergency Priority-A
 - Refresh map
 - Get new MPs
 - Access Teams/Email
 - Sync Work
 - Use Text & Phone
 - Check for changes to weather alerts, roads, safety issues, fire index

End of Shift

- Gather tools & equipment
- Sync Work: While on Cell / WiFi network, ensure all forms & photos are submitted
- Fully charge iOS devices
- Fully charge battery packs
- Secure iOS devices in a locked building



Review MPs / Work Assignments

Review MPs / Work Assignments

- You’ll be assigned to a Main Work Center (MWC)
- Maintenance Plans are electronically dispatched
- Locate your Maintenance Plans using the Inspect App

<input type="checkbox"/> CONCORD	<input type="checkbox"/> EUREKA
<input type="checkbox"/> FRESNO	<input type="checkbox"/> LAKEVILLE
<input type="checkbox"/> MARTIN	<input type="checkbox"/> METCALF
<input type="checkbox"/> MIDWAY	<input type="checkbox"/> MOSS LANDING
<input type="checkbox"/> PISMO BEACH	<input type="checkbox"/> SACRAMENTO
<input type="checkbox"/> TABLE MOUNTAIN	<input type="checkbox"/> VICTOR

ET	Units
T3: MORAGA-CASTRO VALLEY	0 of 32 (0%)
ET	Units
T3: PITTSBURG-SAN RAMON	0 of 24 (0%)
ET	Units
T3: LONE TREE-CAYETANO	0 of 1 (0%)

ET - *TEST GUEST1 T3: GEYSERS #11-EAGLE ROCK*

Annual Climbing Inspections 0/3 units (0%) Due Date 7/31/20 >

S3L1

ET - **TEST GUEST2 AOC: FULTON-PUEBLO**

Detailed Ground Inspections 0/22 units (0%) Due Date 7/31/20 >

S3L1

ET - CLIMB: DIABLO-GATES #1 [PISMOBCH] [YR]

Annual Climbing Inspections 1/255 units (0%) In Progress Due Date 12/31/20 >

S3L1, DEWE, S6KZ, L1LC



Log A Tailboard

Log a Tailboard

Requirements

You are required to submit a Tailboard after you have safely arrived at your first inspection location using the Inspect App “Log a Tailboard”

Workflow

1. You’ve arrived safely at your first inspection location
2. Log a Tailboard using the Inspect App
3. Submit Tailboard

Log a Tailboard

Close

Contact Information

Supervisor's LANID (required)

S6KZ

4/4

Work Details

Type of Work (required)

Annual Inspection

What kind of hazards you might face? (required)

List potential hazards HERE

Location Information

Location

Line Name and Structure #

Review Tailboard



Performing Detailed Inspections

Ground based Non-Climbing Inspection

- Non-destructive visual inspection
- Applies to wood monopoles, wood structures, composite poles, concrete poles, Tubular Steel Pole (TSP), and Light Duty Steel Poles (LDSP)



Hammer Test

PG&E requires a hammer test be performed on all wood poles.

- You are required to always carry a hammer with you when performing inspections on wood poles.
- You will determine the condition of the wood pole by assessing the sound emanating from the quadrants that you strike.
- You must follow the steps outlined below for all wood poles:
 1. Perform a sound inspection (hammer test) for all poles.
 2. Strike the pole on all sides (all four quadrants) with a metal framing hammer (20-ounce minimum) from the groundline to a height of seven feet, or as high as the inspector can reach, whichever is greater.
 3. Ensure that marks from the crosshatched face on the strike plate of the hammer are visible on the pole.
 4. Listen for the sound produced when the hammer strikes the pole to identify the location of possible internal voids or hollows.

IF the pole produces a hollow sound or other sounds that indicate a pole defect, such as internal ruptures, cross breaks, or ring separation at one or more locations.




Then Create a new LC Notification
OR Update the Pending LC
Notification

Reference:	TD-1001M-JA06: Identifying Levels of Damage and Conditions
-------------------	---

Inspections – Checklist

You are required to document your inspection results and provide a standard set of photos using the Inspect App checklist forms.

- Steel/Lattice or LDSP Ground Detailed Inspection Form
- Non-Steel Inspection Form



Inspect

Photo Requirements

During inspection work, photographic images are required of the asset being inspected.

Photos must be:

- Taken of the structure at the location being inspected
- Taken during daylight hours
- Taken so that sunlight does not obscure objects (keep reflective light to a minimum)
- Taken in focus and not blurry or dark
- Zoom-in when necessary for clarity to capture sufficient photo targets (C-Hooks, Hot end shoe, etc.)
- Taken so that objects do not obstruct the target of the photo



Standard Structure Photos – Steel/Lattice/LDSP

Within the Checklist, you will be required to provide a standard set of photos of each Structure being inspected.

Steel/Lattice/LDSP Structure Photo Requirements

1. Take a photo of the Structure number (as visible)
2. Take a photo of the bottom 30 feet of each leg (total 4 legs)
3. Take a photo of the top ½ of the structure, in line with conductors
4. Take a photo of the bottom ½ of the structure, 90° from your last position
5. Photos must be taken within 200' of structure
6. **Use External Cameras** Each photo must be taken separately, no cropping

Standard Structure Photos – Non-Steel

Within the Checklist, you will be required to provide a standard set of photos of each Structure being inspected.

Non-Steel Photo Requirements

1. Take a photo of the Structure number (as visible)
2. Take 2 photos of the first 30 feet of the Structure from the ground up (Take 2 photos of the structure from 2 different angles)
3. Take a photo of the top ½ of the structure, in line with conductors
4. Take a photo of the bottom ½ of the structure, 90° from your last position

5. Use External Cameras

6. Photos must be taken within 200' of structure
7. Each photo must be taken separately, no cropping

Note: Please use long text field noting any field issues/restrictions

Knowledge Check

Let's review:

What pictures are required at every pole?

- A. Structure number (as visible)
- B. Take 2 photos of the structure from 2 angles
- C. Top ½ of the structure, in line with conductors
- D. Bottom ½ of the structure, 90° from your last position
- E. All of the above

Knowledge Check - Answers

Let's review:

What pictures are required at every pole?

- A. Structure number (as visible)
- B. Take 2 photos of the structure from 2 angles
- C. Top ½ of the structure, in line with conductors
- D. Bottom ½ of the structure, 90° from your last position
- E. All of the above



Evaluating Compelling Abnormal Conditions

Assessing Conditions

Factors to Consider When Evaluating a Compelling Abnormal Condition

Asset Inspections are one or more observations, examinations, or tests of a structure and its components in order to identify compelling abnormal conditions requiring action.

- The abnormality encountered
- The risk of exposure to the public, workers, or employees
- Risks if the condition continues to deteriorate
- Potential for the condition to further deteriorate
- Impact of failure to system reliability, customers, and service, and/or the potential for injury

All compelling abnormal conditions requiring action must be acted upon.

The location of the structure and other site-specific conditions will influence the evaluation of the work required.

The priority and recommended repair date, associated with any notification, depends on the proximity to roadways or pedestrian traffic, accessibility of the location to the public, or the impact of failure or exposure.

Assessing Conditions / LCs

How to report Compelling Abnormal Conditions

PG&E uses a notification called a Line Corrective (LC) to document field observations of compelling abnormal conditions.

The Inspector makes repair recommendations using the LC form to capture the Detailed Inspection findings.

When a compelling abnormal condition or non-conformance is identified, create the LC notification using the Inspection software:

- Select the priority code and the conditions to be repaired, replaced, or addressed.
- Add comments describing the condition, access information, and any additional information that will be needed to schedule and perform the work
- Attach a minimum of two field photos

The Centralized Inspection Review Team (CIRT) reviews all notifications and determines work required, if any, and timeframes.

LCs: High Fire Risk Conditions– HFTD Examples

Create LCs for these [fire risk](#) conditions:

- Excessively sagging conductors
- Inadequate separation
- Damaged or deteriorated conductors and associated conductor hardware (e.g., splices, jumpers, dampers).
- Broken insulators compromising insulation values
- Damaged equipment (e.g., switches)
- Damaged or deteriorated crossarms
- Damaged or deteriorated bird guards
- Damaged or excessively leaning towers or poles
- Deteriorated, damaged or excessively leaning towers or tower foundations
- Damaged or broken guys or guy systems (e.g., anchors, splices)
- Equipment found as burnt, flashed, or with evidence of arcing (e.g., insulators, jumpers)
- Sagging guys
- Deteriorated, damaged or missing hardware that creates a fire risk (e.g., could cause structural failure, sparking)
- Insufficient clearance from vegetation
- Vegetation causing strain or abrasion
- Dead trees that could strike facilities
- Broken or exposed ground wire
- Missing or broken bond wire
- Missing or damaged wood pole bridging on under build



LCs: Non-HFTD Examples

Create LCs for these non-fire risk conditions:

- Missing/illegible high voltage sign in remote locations, inaccessible to pedestrians or vehicles
- Missing/illegible high voltage sign on crossarms or poles above legible high voltage marking on lower crossarm(s)
- Missing/illegible/incorrect numbering on poles/tower legs [Marking, Numbering, identification of structures 022168]
- Damaged or missing guy marker in remote locations, inaccessible to pedestrians or vehicles
- Anchor guy with minimal slack where a pole is straight or leaning towards the anchor
- Climbing space obstruction from vegetation when it (1) does not prevent work from being done and (2) does not violate Rule 35
- Damaged, loose, or idle hardware that (1) is not in the climbing space and (2) does not pose a risk to employees or the public
- Missing or damaged bolt covers where only exposure is to the QEWs
- Exposed ground rod in inaccessible or remote location
- Access (e.g., damaged gate) that does not pose a risk to employees of the public

LCs – Assigning Priorities and FDAs

ETMP Manual will provide a list of FDA's:

- **Facility:** The component being inspected
- **Damage:** The code assigned to defective element found during inspection or patrol
- **Action:** Required action(s) to correct identified abnormal condition

If more than one action is required at a facility, then each must be identified.

Table 2. Overhead Facility, Damage, and Corrective Action Codes

Facility	Damage	Action
Anchor-Steel	Missing	Install
	No Good/Out of Std	Repair Replace
Anchor-Wood	Missing	Install
	No Good/Out of Std	Repair Replace
Animal Guard-Steel	Missing	Install
Animal Guard-Wood	Missing	Install
Anode-Tower	Missing	Install
	No Good/Out of Std	Repair Replace

Reference	TD-1001M: ETPM, Table 2. Overhead Facility, Damage, and Corrective Codes , pp. 13-14
-----------	--

Using Table 3: Priority Codes

Table 3 Priority Codes

Priority Code	G.O. 95, Rule 18 Level	Priority Description – Time Frame ¹
A	1	The condition is urgent and requires immediate response and continued action until the condition is repaired or no longer presents a potential hazard. SAP due date is 30 days – to allow time for post-construction processes and notification close-out.
B	-	Not used for maintenance corrective action priority.
E	2	Corrective action is required, as follows: <ul style="list-style-type: none"> • Within 6 months for HFTD Tier 3² • Within 12 months for HFTD Tier 2/HFRA/Zone 1 ² • Within 12 months for potential violations that compromise worker safety • Within 36 months for all other potential violations
F	3	Corrective action is required within 60 months.

Note that Priority E Notifications are time dependent depending on HFTD/HFRA/Zone 1. Safety concerns are also considered

1-Time frames listed are “Not to Exceed” and QCR/CIRT may define time frames according to site-specific conditions.

2- IF the condition in the HFTD Tier 3 OR Tier 2/HFRA/Zone 1 does not create a fire risk (non-threatening), THEN the corrective action is required **within 36 months**.

Reference	Please refer to TD-8123P-103: “Electric Transmission Line Guidance for Setting Priority Codes”
------------------	--

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
<p>Anchor-Steel (ANCS)</p> <p>Anchor-Wood (ANCW)</p> <p>Note: Anchor head buried (per Numbered Document 025998, e.g., incomplete inspection)</p> <p>See Job Aid TD-1001M-JA13.</p>	<p>> 50% Material loss</p>	<ul style="list-style-type: none">• 25–50% Material loss.• Anchor rod concrete has significant cracking; needs repair and resealing.• Soil movement/slide.• Guy anchor being pulled out.• Twisted/bent anchor rod.	<ul style="list-style-type: none">• 15–25% Material loss• Anchor rod concrete has minor cracking; needs resealing.• Anchor rod in concrete not sealed in corrosive environments.• Re-seal deteriorated mastic.

^[1] For Action Code abbreviations, use INST (Install), REPA (Repair), REPL (Replace)
^[2] Return to field for completion. Do not process notification (keep in S5 status) until completed in field and anchor condition is identified.
^[3] For geotechnical concerns, contact civil engineering and geosciences personnel.

Reminder	Inspector’s primary responsibility in an overhead electric facility inspection or patrol is to examine and record the specific condition of the facilities.
----------	---

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Guy Wire-Steel (GYWS) Guy Wire-Wood (GYWW) See Job Aid ID-1001M-JA13 .	<ul style="list-style-type: none"> • > 50% Material loss • Broken or missing load bearing guy 	<ul style="list-style-type: none"> • 25–50% Material loss • Broken or missing storm guy where required • Slack or overtension guys ⁴ • Clearance from energized conductor • Framing configurations where a bird can land and reach energized parts and guy bonded and not sectionalized (e.g., does provide a path to ground). ⁵ • Guy insulator in poor condition • Preform grips not in thimbles • Preform cross ties not properly installed • Where automatic guy strand dead ends and splices exist, follow Job Aid ID-1001M-JA13. 	<ul style="list-style-type: none"> • 15–25% Material loss • Fiberglass rod not installed or installed in wrong position ⁵ • Turnbuckle out of threads

⁴ For slack or overtension load bearing guys, recommend to address within 3 months.

⁵ Follow guidance in [Numbered Document 022178](#).

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Conductor-Steel (CONS) Conductor-Wood (CNDW) Shield Wire/OPGW, ADSS, non-ADSS lashed ⁶ (SHLS) (SHLW) Jumpers (JUMS) (JUMW) Tie Wire (TIES, TIEW) Ground Wire (GRWS, GRWT, GRWW) See Job Aids TD-1001M-JA10 and TD-1001M-JA11 .	<ul style="list-style-type: none"> • > 50% Material loss • Broken strands and out-of-lay strands (e.g., gunshot) > 40%, Numbered Document 028855 • Active arcing • Broken or loose tie wire (conductor not well seated in the saddle with vertical load or not fully captured with tie wire) 	<ul style="list-style-type: none"> • 10–50% Material loss • Broken strands and out-of-lay strands (e.g., gunshot) 5–40%, Numbered Document 028855 • Evidence of arcing ⁷ • Broken or loose tie wire (conductor well seated in the saddle with vertical load or partially captured with tie wire) • Broken ground wire ⁸ • Loose connector or weight • Twisted bundled conductor ⁷ • Conductor kinked/pinched at clamp • Vibrating (send to engineering personnel for evaluation) • Ground wire in poor condition (corrosion, flashed, missing) 	<ul style="list-style-type: none"> • Broken strands and out-of-lay strands (e.g., gunshot); Numbered Document 028855 • Uneven sag (send to engineering personnel for evaluation)

⁶ For OPGW, ADSS, and non-ADSS lashed fiber cable, refer to the associated job aids referenced in Section 2.4.8 of the *ETPM Manual* for specific conditions and priorities.

⁷ Recommend to address within 3 months.

⁸ Consider elevating tag priority if condition represents imminent risk to public safety (i.e., break near ground level in urban setting).

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Damper-Steel (DAMS) Damper-Wood (DAMW) Spacers (SPAS, SPAW)		<ul style="list-style-type: none"> Broken spacer Broken/missing/out of position damper Bent > 45 degrees damper Missing spacer (where required) 	
Splices (SPLS) (SPLW) See Job Aids TD-1001M-JA14 and TD-1001M-JA19	<ul style="list-style-type: none"> > 50% Material loss Very hot (> 100-degree differential) 	<ul style="list-style-type: none"> Hot (< 100-degree differential) ⁹ Any visible damage to splice Automatic Splice Any splice < 10 feet to clamp 	
Electrical clearances: GO95 Clear Infract-Tower (GO9S) GO95 Clear Infract-Wood (GO9W) Right of Way (ROW1) Vegetation (VEGN) Vegetation-Tower (VEGT) See Job Aids TD-1001M-JA10 and TD-1001M-JA20	<ul style="list-style-type: none"> Tree contacting line or showing signs of contact (burnt leaves or limbs) Encroachments 	<ul style="list-style-type: none"> Trees clearance < G.O. 95 or PG&E-required Circuit-to-circuit Burnt Ground clearance < G.O.95 or PG&E-required Grade change (ground clearance < G.O.95 or PG&E-required) Significant vegetation around base of structure; may be impacting climbing or ability to inspect base of structure Jumper clearance less than requirement; Numbered Document 068177 	Encroachments to be resolved via Land Management

⁹ Recommend to address within 3 months.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Foundation/Concrete-Tower (FOND) ¹⁰ Note: Earth covered/buried foundation (covering steel member) (incomplete inspection) ¹¹ Direct Buried Grillage Note: Uncover 6 inches to determine conditions. If no issue, rebury, no tag needed. Based on condition seen, if additional excavation needed, expose stub < 18 inches ¹² See Job Aid TD-1001M-JA12	<ul style="list-style-type: none"> Significant soil erosion or movement causing lack of support around the foundation ¹³ Damage to, or separation of, main structural support members or stub angle tower leg that compromised structural integrity Direct buried grillage > 50% material loss 	<ul style="list-style-type: none"> Soil movement (e.g., movement causing bowing of tower members) ¹³ Erosion (vertical) > 3 feet ¹³ Slide 10–15 inches ¹³ Direct buried grillage rust, 30–50% material loss Stub in concrete, has significant cracking, needs repair and resealing Rebar exposed with > 50% material loss 30–50% material loss of foundation or stub Buckled rebar, concrete spalling Cracked (cracks > 1/8 inch) ¹⁴ Exposed wood pile (contact civil engineering personnel for assessment) Rotated 	<ul style="list-style-type: none"> Erosion 1–3 feet ¹³ Stub in concrete, has minor cracking, needs resealing Stub in concrete needs resealing Cracked (cracks 1/16–1/2 inch)

¹⁰ For structural integrity or other significant concerns, request an engineering assessment by directly contacting civil engineering or through the local supervisor.

¹¹ Return to field for completion. Do not process (keep in S5 status) until completed in field and foundation condition is identified.

¹² Less than 18 inches minimizes the need for extensive excavation that could compromise tower stability and compaction effort.

¹³ For geotechnical concerns, contact civil engineering and geosciences personnel.

¹⁴ For cracks that extend to the stub, recommend to address within 3 months.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Insulator (INSU) Insulator-Steel (INSS) Insulator-Wood (INSW) Note: For insulators that are flashed, cracked, broken, gunshot, or chipped > 1-1/2 inches, see Job Aid TD-1001M-JA07 .	<ul style="list-style-type: none"> > 50% Material loss Contaminated (arcing) 	<ul style="list-style-type: none"> 30–50% Material loss Contaminated (heavy) ¹⁵ Tracking (heavy) Missing/loose cotter key in retainer pin ¹⁶ Out-of-plumb, post or suspension insulator, exhibiting signs of impacting conductor Chalking/cracking on polymer ¹⁷ Corona rings damaged, missing (where required), or improperly installed (500 kilovolt [kV] only) 	<ul style="list-style-type: none"> Contaminated (medium) Tracking (medium) Out-of-plumb post insulator > 6 inches

¹⁵ Recommend to address heavy guano contamination within 3 months.

¹⁶ Other missing or loose cotter key configurations will be prioritized based on site-specific conditions.

¹⁷ Recommend to address within 12 months.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Hardware (HRDS) (HRDT) (HRDD) Bolts, J-Bolts, U-Bolts, links, clamps, hot-end or cold-end hardware, shoe assembly, shackles, cotter key/pin, turnbuckle Hanger Plates Job Aid TD-1001M-JA07.	<ul style="list-style-type: none"> • > 50% Material loss • Cracked > 50% • Contaminated (arcing) • Cotter key missing and retainer pin not fully seated • < ¼ inch material remaining on plate ^{18, 19} 	<ul style="list-style-type: none"> • 30–50% Material loss ²⁰ • Cracked 5–50% ²⁰ • Missing cotter key or loose cotter key in retainer pin ²¹ • ¼– ½ inch material remaining on plate ^{18, 20} • Missing hardware (if necessary, send to engineering personnel for evaluation) 	Loose

¹⁸ Thickness of material (i.e., plate thickness) can determine if Priority A or Priority E. A relatively thin plate (e.g., less material) is a Priority A.

¹⁹ For legacy towers designed with ½ inch starting hanger plate material (e.g., San Joaquin Light and Power K-type towers found on Coalinga #1-San Miguel 70 kV and Wishon-Coppermine 70 kV, but not limited to), Priority E is adequate for 1/4–3/8-inch material remaining.

²⁰ Recommend to address within 3 months.

²¹ Other missing or loose cotter key configurations will be prioritized based on site-specific conditions.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Switch (SWTC) Switch-Steel (SWIS) Switch-Wood (SWIW) Note: For switch insulators that are flashed, cracked, broken, gunshot, or chipped >1-1/2 inches, see Job Aid TD-1001M-JA07 . SCADA-Steel (SCDS) SCADA-Wood (SCDW) See Job Aid TD-1001M-JA15 .	<ul style="list-style-type: none"> • > 50% Material loss • Cracked > 50% • Arcing or evidence of arcing • Switch operating mechanism unlocked • Inoperable • Out of adjustment (blades and load break devices not fully seated) • Missing/damaged switch attachment ²² • Inform GCC that SCADA is not operational (no tag required unless instructed) 	<ul style="list-style-type: none"> • 30–50% Material loss • Cracked 5–50% • Contaminated (heavy) • Tracking (heavy) • Loose/broken/missing parts or hardware • Heating • Bent/bowed control rod or platform • Switch handle not bonded to platform ²³ 	<ul style="list-style-type: none"> • Contaminated (medium) • Tracking (medium)

²² Priority A may be addressed by contacting the GCC and marking the switch inoperable with a caution tag and repair tag time frame as appropriate.

²³ For switch handles not bonded to platform, address within 12 months.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Structure-Steel (STRS)²⁴ Structure-Tower (STRT)²⁵ Shield Wire Plates Crossarms (CRSL, CRST) See Job Aid ID-1001M-JA04	<ul style="list-style-type: none"> • Critical/main member: <ul style="list-style-type: none"> ◦ > 50% Material loss ◦ Cracked > 50% ◦ Broken/missing • Severe damage to main structural support members compromising structural integrity (stub, leg, cross arm) • Internal corrosion of tubular members 	<ul style="list-style-type: none"> • 30–50% Material loss • Cracked 10–50% • Broken/missing secondary member • Moderate damage to main structural support members compromising structural integrity (stub, leg, cross arm) ²⁶ • H-Frame cross-brace broken • Missing bolts on single bolt connection on critical member • Pack-rust at joints, crevices, or overlaps ²⁷ • Buckled/bent secondary member • Out of plumb (send to engineering personnel for evaluation) • Twisted 	<ul style="list-style-type: none"> • Single bolt missing of multi-bolt connection • Loose bolts • Vibrating members • Climbing steps in poor condition • Paint/galvanizing finish deteriorating and little rust or metal loss
Markers (i.e., signs)-Steel (MRKS) Markers (i.e., signs)-Wood (MRKW) Guy Markers (GMKS, GMKW) FAA Lighting and Batteries	Facilities or structures with a recent history of trespass or third-party unauthorized access	<ul style="list-style-type: none"> • Marker balls in poor condition and wearing on conductor • Marker balls damaged • FAA battery no good; FAA lighting missing or no good 	<ul style="list-style-type: none"> • Anti-climbing guards broken, cracked, damaged • Anti-climbing guards missing where required, per ID-1009S-F01 • Cracked, broken, loose, missing

²⁴ For hanger plates, refer to the [Hardware section](#) of this table (Page 14).

²⁵ For structural integrity or other significant concerns, request an engineering assessment by directly contacting civil engineering or through the local supervisor.

²⁶ For damage to main structural support members compromising structural integrity that is not an immediate risk, address within 3 months.

²⁷ Contact civil engineering for further assessment.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Road (ROAD)	Posing threat to facilities due to wash-out or land motion.		Access road repair or replacement
Structure-Wood (STRW) Guy Stub (STUS, STUW) (Also referred to as Guy Pole) Note: Includes pole, crossarms (CRSW, CRSL), bonding, bearing plates. SEE Job Aid TD-1001M-JA06	<ul style="list-style-type: none"> Burnt/rotten > 50% material loss Crossarm bracing missing or broken, compromising insulator and conductor Bond wire broken < ¼ inch gap Severe pole top damage or split top, compromising hardware, or crossarm integrity Cracked (not checks) Broken 	<ul style="list-style-type: none"> Burnt/rotten 20–50% material loss Crossarm bracing loose/missing Bond wire broken > ¼-inch gap Pole top damage or split top, compromising hardware or crossarm integrity ²⁸ Twisted H-Frame cross brace broken or missing ²⁸ Out of plumb > 3 feet and causing insulators and conductor to be compromised ²⁸ Slide > 5 feet ²⁹ Soil movement (erosion > 3 feet in the ground) ²⁹ Worn/woodpecker/insect damage (severe and/or near hardware) Standing water (not including seasonal conditions) Ground molding in poor condition or missing 	<ul style="list-style-type: none"> Slide 1–5 feet ²⁹ Soil movement (erosion 1–3 feet in the ground) ²⁹ Worn/woodpecker/insect damage (medium or minor damage near hardware) Climbing steps in poor condition

²⁸ Recommend to address within 3 months.

²⁹ For geotechnical concerns, contact civil engineering and geosciences.

Using Table 4 – Guide for Assigning Priority Codes

Table 4 Updates

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Structure (Fiberglass, Composite, or Concrete)	<ul style="list-style-type: none"> • Crossarm bracing broken/missing causing insulator and conductor to be compromised • Buckled (deformation) 	<ul style="list-style-type: none"> • Cracked fiberglass ³⁰ • Cracked concrete into rebar ³⁰ • Out of plumb > 3 feet and causing insulators and conductor to be compromised ³¹ • Soil movement (erosion > 3 feet in the ground) ³² • Slide > 5 feet ³² • H-Frame cross brace broken or missing ³¹ • Crossarm bracing loose/missing 	<ul style="list-style-type: none"> • Cracked concrete (cracks > ½ inch) not into rebar ³⁰ • Soil movement (erosion 1–3 feet in the ground) ³² • Slide 1–5 feet ³² • Pole access device or climbing steps in poor condition
Idle Facilities (any facility type) (De-energized) See ID-1003P-01, "Management of Idle Electric Transmission Line Facilities."	Removal of idle facilities posing an immediate threat to life, property, or reliability.		Removal of non-emergency idle facilities.

³⁰ Contact civil engineering for further assessment

³¹ Recommend to address within 3 months.

³² For geotechnical concerns, contract Civil Engineering and Geosciences.

Knowledge Check

Let's review:

What does FDA mean and when is it used?

- A. Foundation, Damage, A-Priority and is used when creating an LC Notification for a damaged foundation
- B. Facility, Damage, Action Code and is used when an LC Notification is created
- C. Found Damaged Asset and is noted in the Comments section in the Inspect App
- D. None of the above

Knowledge Check - Answers

Let's review:

What does FDA mean and when is it used?

- A. Foundation, Damage, A-Priority and is used when creating an LC Notification for a damaged foundation
- B. Facility, Damage, Action Code and is used when an LC Notification is created
- C. Found Damaged Asset and is noted in the Comments section in the Inspect App
- D. None of the above

Knowledge Check

Let's review:

Where can you find the FDA Priority?

- A. ETPM Table 4
- B. Five Minute Meeting (5MM)
- C. Federal Department of Agriculture

Knowledge Check - Answers

Let's review:

Where can you find the FDA Priority?

- A. ETPM Table 4
- B. Five Minute Meeting (5MM)
- C. Federal Department of Agriculture

Knowledge Check

On Steel Structures, broken/missing secondary members constitute what priority?

- A. A (Level 1 – Immediate)
- B. E (Level 2 – 6/12/36 Months)
- C. F (Level 3 – 60Months)

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Structure-Steel (STRS)²⁴ Structure-Tower (STRT)²⁵ Shield Wire Plates Crossarms (CRSL, CRST) See Job Aid TD-1001M-JA04	<ul style="list-style-type: none"> • Critical/main member: <ul style="list-style-type: none"> ◦ > 50% Material loss ◦ Cracked > 50% ◦ Broken/missing • Severe damage to main structural support members compromising structural integrity (stub, leg, cross arm) • Internal corrosion of tubular members 	<ul style="list-style-type: none"> • 30–50% Material loss • Cracked 10–50% • Broken/missing secondary member • Moderate damage to main structural support members compromising structural integrity (stub, leg, cross arm) ²⁶ • H-Frame cross-brace broken • Missing bolts on single bolt connection on critical member • Pack-rust at joints, crevices, or overlaps ²⁷ • Buckled/bent secondary member • Out of plumb (send to engineering personnel for evaluation) • Twisted 	<ul style="list-style-type: none"> • Single bolt missing of multi-bolt connection • Loose bolts • Vibrating members • Climbing steps in poor condition • Paint/galvanizing finish deteriorating and little rust or metal loss

Knowledge Check - Answers

On Steel Structures, broken/missing secondary members constitute what priority?

- A. A (Level 1 – Immediate)
- B. **E (Level 2 – 6/12/36 Months)**
- C. F (Level 3 – 60Months)

Component ¹	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Structure-Steel (STRS)²⁴ Structure-Tower (STRT)²⁵ Shield Wire Plates Crossarms (CRSL, CRST) See Job Aid TD-1001M-JA04	<ul style="list-style-type: none"> • Critical/main member: <ul style="list-style-type: none"> ◦ > 50% Material loss ◦ Cracked > 50% ◦ Broken/missing • Severe damage to main structural support members compromising structural integrity (stub, leg, cross arm) • Internal corrosion of tubular members 	<ul style="list-style-type: none"> • 30–50% Material loss • Cracked 10–50% • Broken/missing secondary member • Moderate damage to main structural support members compromising structural integrity (stub, leg, cross arm) ²⁶ • H-Frame cross-brace broken • Missing bolts on single bolt connection on critical member • Pack-rust at joints, crevices, or overlaps ²⁷ • Buckled/bent secondary member • Out of plumb (send to engineering personnel for evaluation) • Twisted 	<ul style="list-style-type: none"> • Single bolt missing of multi-bolt connection • Loose bolts • Vibrating members • Climbing steps in poor condition • Paint/galvanizing finish deteriorating and little rust or metal loss



Identifying Compelling Abnormal Conditions

Using Job Aids and Examining Photos

- The Job Aids provide guidance on whether the location of the condition will impact safety reliability and fire risk.
- Using the Pictures in the Job Aid, the Inspector compares them to the current Compelling Abnormal Condition found in the field and determines the Priority Code.

Job Aids are accessible via:

- **SMW**
- **TIL & Mobile TIL**
- **Teams Channel**

Job Aid Documents

List of Job Aids within the ETMP [TD-1001M]

- TD-1001M-JA1
- TD-1001M-JA2
- TD-1001M-JA3
- TD-1001M-JA4
- TD-1001M-JA6
- TD-1001M-JA7
- TD-1001M-JA8

- TD-1001M-JA9
- TD-1001M-JA10
- TD-1001M-JA11
- TD-1001M-JA12
- TD-1001M-JA13
- TD-1001M-JA14
- TD-1001M-JA15

- *TD-1001M-JA16
- *TD-1001M-JA17
- *TD-1001M-JA18
- TD-1001M-JA19
- TD-1001M-JA20
- TD-1001M-JA21
- TD-1001M-JA22
- TD-1001M-JA23

* Denotes the Job Aid is for Underground Conditions

Job Aid Number	Title	Date
TD-1001M-JA11	Evaluating Conditions of OPGW in Transmission Line	04/07/2022
TD-1001M-JA21	Evaluating Conditions of ADSS in Transmission Line	08/31/2020
TD-1001M-JA22	Evaluating Conditions of Non-ADSS Lashed Fiber Cable in Transmission Line	08/31/2020


2023 Updated Job Aid Documents

Job Aid Number	Title	Date
TD-1001M-JA04	Identifying Levels of Deterioration and Corrosion on Transmission Line Steel Structures and Supports	01/20/2023
TD-1001M-JA06	Identifying Levels of Damage and Condition on Wood Poles and Non-Steel Framing on Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA07	Identifying Levels of Corrosion and Condition of Hardware and Insulators on Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA08	Identifying Levels of Damage and Condition of Animal Guards on Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA09	Identifying Maintenance Work on Bird Nests on Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA10	Identifying Conductor Conditions	01/20/2023
TD-1001M-JA12	Identifying Foundation Condition on Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA13	Identifying Levels of Damage and Condition of Guys and Anchors of Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA14	Identifying Levels of Damage and Condition of Splices on Transmission Line Structures and Supports	01/20/2023
TD-1001M-JA15	Identifying Levels of Deterioration and Corrosion on Transmission Line Switches	01/20/2023
TD-1001M-JA19	Evaluating Conditions from Infrared (IR) Inspection in Transmission Line	01/20/2023
TD-1001M-JA20	Evaluating Conditions for Vegetation Nonconformances in Transmission Lines	01/20/2023

Job Aid Outline

Job Aid Template

1. Published Date & No.
2. PPE
3. Tools
4. Guidance Document References
5. Level of Use
6. Purpose
7. Condition Codes

 Evaluating Conditions for Vegetation Nonconformances in Transmission Lines 1 TD-1001M-JA20 Published: 01/20/2023 Effective: 02/20/2023 Rev: 1		
2 PPE: Standard T-Line PPE, including <ul style="list-style-type: none">• Hard hat• Safety glasses• Gloves• FR clothing	3 Tools: <ul style="list-style-type: none">• Camera	4 Guidance Document References: TD-1001M, "Electric Transmission Preventive Maintenance Manual"
5 Level of Use: <input type="checkbox"/> Information <input checked="" type="checkbox"/> Reference <input type="checkbox"/> Continuous		

6 **Purpose:**


This job aid provides the instructions and requirements for routine inspection of vegetation around PG&E electric transmission lines to ensure the safe and reliable operation of facilities.

7 **Condition Codes:**

Inspect the structure using the form to record issues. Determine the condition of each item. Consider all conditions to determine the appropriate Priority Code for any notification, if required.

- 5 = Heavy damage with safety concerns
- 4 = Heavy damage
- 3 = Moderate damage
- 2 = Light damage
- 1 = No visible damage

Identifying Levels of Corrosion and Foundation Condition: Job Aids



Identifying Levels of Deterioration and Corrosion on Transmission Line Steel Structures and Supports

TD-1001M-JA04
Published: 01/20/2023
Effective: 02/20/2023
Rev: 3

PPE:

Standard T-Line PPE including:

- Hard hat
- Safety glasses
- Gloves
- FR clothing
- Safety boots
- Fall protection

Tools:

- Dull putty knife (screwdriver or similar device)
- Binoculars
- Camera
- Rags

Guidance Document References:

[TD-1001M, Electric Transmission Preventive Maintenance Manual](#)

Purpose:

This job aid provides steps for consistent evaluation of rust and corrosion on (T-Line) lattice towers, lattice poles, steel poles, and supports. The evaluation classifies the severity and potential impact of the rust, corrosion or deterioration, and provides the description of each condition level. The Qualified Company Representative (QCR) combines foundation condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level. The QCR should use this guide to select the appropriate condition representing the as-found deterioration or corrosion level for assigning the recommended priority code. Follow instructions in the [ETPM Manual](#), in conjunction with this job aid, to document the condition(s) on an SAP notification.

For structural integrity or other significant concerns, request an evaluation from the civil engineering directly or through the local supervisor.



Identifying Foundation Condition on Transmission Line Foundations

TD-1001M-JA12
Published: 01/20/2023
Effective: 01/20/2023
Rev: 1

PPE:

Standard T-Line PPE, including

- Hard hat
- Safety glasses
- Gloves
- FR clothing
- Safety boots
- Fall protection

Tools:

- Dull putty knife (screwdriver or similar device)
- Binoculars
- Camera
- Rags

Guidance Document References:

[TD-1001M, Electric Transmission Preventive Maintenance Manual](#)

Level of Use:

- ☐ Information
- ☒ Reference
- ☐ Continuous

Purpose:

This job aid provides the steps for consistent evaluation of foundation conditions. The evaluation classifies the severity and potential impact of the deterioration and provides the description of each condition level. The Qualified Company Representative (QCR) combines foundation condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level.


The QCR should use this guide to select the appropriate condition representing the as-found deterioration level for assigning the recommended priority code. Follow instructions in the [ETPM Manual](#), in conjunction with this job aid, to document the condition(s) on an SAP notification.

Examples: Corrosion



**BROKEN
MEMBER
CONDITION 5**

**RUSTED
OFF**



**ISOLATED EROSION,
CRACKING,
PEELING.
CONDITION 2**



**LOCALIZED
CORROSION. SOME
METAL LOSS.
CONDITION 3**

Great examples, but the corrosion and the cracks may not be this apparent.




Examples: Minor Corrosion



Note – Condition 2: Minor Corrosion with no pits, Add Field Comments to indicate “Minor corrosion”

Examples: Bracing and Sways



If you believe an engineering analysis is required, include the following comments in your LC: "May Need Engineering Analysis"

Examples: Foundation



**RUSTED OFF AND
FOUNDATION
CRUMBLING
CONDITION 5**



**EXPOSED
REINFORCING
STEEL
CONDITION 4**



**EARTH
COVERED
STUBS
CONDITION 3**



**CRACKS >
1/16"
CONDITION 3**

CONFIDENTIAL – Provided Pursuant to Confidentiality Declaration (“WMP-Discovery2023-2025_DR_CalAdvocates_046_Delivery 2_Confidentiality Declaration.pdf”)

Job Aid: Examining the Steel Structure & Foundation

Corrosion and Structure Condition Levels and Impact (continued)

Condition 4

1 Heavy damage. Severe corrosion with possible near-term impact to safety, facility integrity, or operations.

- 30–50% material loss
- Cracked 10–50%
- Broken/missing secondary member
- Moderate damage to main structural support members compromising structural integrity (stub, leg, crossarm) (recommended to address within 3 months)
- H-Frame cross-brace broken
- Missing bolts on single bolt connection on critical member
- Pack rust at joints, crevices, or overlaps*
- Buckled/bent secondary member
- Out of plumb (send to engineering personnel for evaluation)
- Twisted

***NOTE:** Contact civil engineering for further assessment.

Action:

1. Request engineering assessment of the structural integrity.
2. Take photos of damage.
3. Choose Priority Code E.
4. Choose shortened due date (3–12 months) based on conditions and location.

2 Moderate damage to tower crossarm
FDA: Structure-Tower | No Good | Repair

3 Severe pack rust at joints
FDA: Structure-Tower | No Good | Repair

NOTE

For hanger plate conditions, refer to [Job Aid TD-1001M-JA07, “Identifying Levels of Corrosion and Condition of Hardware and Insulators on Transmission Line Structures and Supports.”](#)

1. Condition
2. FDA
3. FDA
4. Priority - Duration

Foundation Condition Levels and Impact

Condition 5

1 Severe deterioration with an immediate safety concern OR potential to impact operations.

- Significant soil erosion or movement causing lack of support around the foundation.*
- Damage to, or separation of, main structural support members or stub angle tower leg that compromised structural integrity.
- Direct buried grillage rust, corrosion > 50% material loss

*** NOTE:** For geotechnical concerns, contact Civil Engineering and Geosciences.

Action:

1. Request engineering assessment of the structural integrity.
2. Take photos of damage.
3. Choose Priority Code A.

2 Corroded stub in concrete, >50%
FDA: Emergency | Storm-Related | Repair

3 Corroded stub in concrete, >50%
FDA: Emergency | Storm-Related | Repair

Identifying Maintenance Work on Bird Nests: Job Aids



Identifying Maintenance Work on Bird Nests on Transmission Line Structures and Supports

TD-1001M-JA09

Published: 01/20/2023

Effective: 02/20/2023

Rev: 1

PPE: Standard T-Line PPE, including <ul style="list-style-type: none"> Hard hat Safety glasses Gloves FR clothing Safety boots Fall protection 	Tools: <ul style="list-style-type: none"> Binoculars Camera 	Guidance Document References: TD-1001M, Electric Transmission Preventive Maintenance Manual
		Level of Use: <ul style="list-style-type: none"> <input type="checkbox"/> Information <input checked="" type="checkbox"/> Reference <input type="checkbox"/> Continuous

Purpose:

This job aid provides the steps for consistent evaluation of maintenance work on bird nests on transmission line (T-Line) structures. The evaluation assesses the potential impact of the presence of bird nests. The Qualified Company Representative (QCR) combines bird nest condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level.

Follow instructions in the [ETPM Manual](#), in conjunction with this job aid, to document the condition(s) on an SAP notification.

NOTE

Contact the Avian Manager before the removal of ANY nest.

Bird Nests on Transmission Line Structures: Job Aid

Job Aid [TD-1001M-JA09] Identifying Maintenance Work on Bird Nests on Transmission Line Structures and Supports

Job Aid Guide:

1. Condition is Listed – 4
2. Recommended FDA Provided
3. Recommended FDA Provided
4. Priority & Duration Provided

1 Assessing the Impact of Bird Nests


Condition 4

Bird nests pose an electrical threat with urgent action required.

- Nest is within switching components, bird contact may occur during switching
- Nest is large enough to break minimum clearance requirements
- Nesting perch is damaged, threatens conductor


4 Action:

1. Take photos of nest.
 - Ensure that the location of nest with respect to the rest of the structure is properly captured.
1. Choose Priority Code E.
2. Choose shortened due date (3–12 months) based on conditions and location.



40646627


Large nest on crossarm
FDA: Structure-Wood | Debris/Nest | Remove




40585414

Nest is on a switch arm
FDA: Structure-Wood | Debris/Nest | Remove

Evaluating Conditions of OPGW

 Evaluating Conditions of OPGW in Transmission Line		TD-1001M-JA11 Published: 04/07/2022 Effective: 06/07/2022 Rev: 3
PPE: Standard T-Line PPE, including: <ul style="list-style-type: none">• Hard Hat• Safety Glasses• Gloves• FR clothing	Tools: <ul style="list-style-type: none">• Binoculars• Camera	Guidance Document References: TD-1001M, “Electric Transmission Preventative Maintenance Manual” Level of Use: <ul style="list-style-type: none"><input type="checkbox"/> Information<input checked="" type="checkbox"/> Reference<input type="checkbox"/> Continuous
Purpose: <p>This job aid provides consistent evaluation of overhead ground wire/fiber optic cable (OPGW) in transmission lines, and consistent decision-making.</p> <p>The Qualified Company Representative (QCR) should use this guide to evaluate the condition of OPGW, confirm proper application, select the appropriate condition representing the deterioration level, and consistently assign the priority code.</p> <p>The QCR should use this guide to select the appropriate condition representing the as-found OPGW condition for assigning the recommended priority code.</p>		

Evaluating Conditions of ADSS in Transmission Line

 Evaluating Conditions of ADSS in Transmission Line		TD-1001M-JA21 Effective: 08/31/2020, Rev: 0
PPE: Standard T-Line PPE, including: <ul style="list-style-type: none">• Hard Hat• Safety Glasses• Gloves• FR clothing	Tools: <ul style="list-style-type: none">• Binoculars• Camera	Guidance Document References: TD-1001M, “Electric Transmission Preventative Maintenance Manual”
		Level of Use: <ul style="list-style-type: none"><input type="checkbox"/> Information<input checked="" type="checkbox"/> Reference<input type="checkbox"/> Continuous
Purpose: <p>This job aid provides consistent evaluation of all dielectric self-supporting cable (ADSS) in transmission lines, and consistent decision-making.</p> <p>The Qualified Company Representative (QCR) should use this guide to evaluate the condition of ADSS, confirm proper application, select the appropriate condition representing the deterioration level, and consistently assign the priority code.</p> <p>The QCR should use this guide to select the appropriate condition representing the as-found ADSS condition for assigning the recommended priority code.</p>		

Evaluating Conditions of Non-ADSS Lashed Fiber Cable in Transmission Line



Evaluating Conditions of Non-ADSS Lashed Fiber Cable in Transmission Line

TD-1001M-JA22

Effective: 08/31/2020, Rev: 0

PPE:

Standard T-Line PPE,
including

- Hard Hat
- Safety Glasses
- Gloves
- FR clothing

Tools:

- Binoculars
- Camera

Guidance Document References:

TD-1001M, “Electric Transmission
Preventative Maintenance Manual”

Level of Use:

- ☐ Information
- ☒ Reference
- ☐ Continuous


Purpose:

This job aid provides consistent evaluation of non-all dielectric self-supporting (non-ADSS) lashed fiber cable in transmission lines, and consistent decision-making.

The Qualified Company Representative (QCR) should use this guide to evaluate the condition of non-ADSS lashed fiber cable, confirm proper application, select the appropriate condition representing the deterioration level, and consistently assign the priority code.



The QCR should use this guide to select the appropriate condition representing the as-found non-ADSS lashed fiber cable condition for assigning the recommended priority code.

Overhead Ground Wire, OPGW and ADSS Cable Inspection



Examples: OPGW / ADSS Cable Issues


BROKEN STRANDS



SPACER BAR DIGGING INTO CABLE




Examples: Buffer Tube Issues - OPGW



OUTER LAYER
OPGW STRANDS

EXPOSED
STAINLESS
STEEL
BUFFER TUBE


FAILED CABLE
DUE TO
TRACKING



SIGNS OF
TRACKING



Example of Broken Lashing



Examining the Cable and Hardware Installation

Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Signs of: <ul style="list-style-type: none">• Tracking• Broken strands• Separating strands• Bare fiber• Exposed buffer tubes	Yes	Shield Wire/OPGW- Steel or Wood	No Good/Out of Std	Repair

Requirements:

- You are required to provide recommendations for action
- You are required to add field comments, a map screenshot and two field photos of the condition(s)

Condition of Guys & Anchors



Identifying Levels of Damage and Condition of Guys and Anchors on Transmission Line Structures and Supports

TD-1001M-JA13

Published: 01/20/2023

Effective: 02/20/2023

Rev: 3

PPE:

Standard T-Line PPE, including:

- Hard hat
- Safety glasses
- Gloves
- FR clothing
- Safety boots
- Fall protection

Tools:

- Binoculars
- Camera
- Shovel

Level of Use:

- ☐ Information
- ☒ Reference
- ☐ Continuous

Guidance Document References:

- [TD-1001M, "Electric Transmission Preventive Maintenance Manual"](#)
- [Numbered Document 06537, "Guy Grips, Clamps, and Splices"](#)

Purpose:

This job aid provides steps for consistent evaluation of damage on guys and anchors on transmission line (T-Line) structures. The evaluation classifies the severity and potential impact of the damage or deterioration and provides the description of each condition level. The Qualified Company Representative (QCR) combines the condition of guys and anchors with other as-found conditions and risk factors to assess and recommend the appropriate priority level.

The QCR should use this guide to select the appropriate condition representing the as-found damage or deterioration level for assigning the recommended priority code. When choosing the priority code, consider if the location is in a corrosive environment, such as coastal, heavy agricultural pollution, etc., which can accelerate deterioration. Follow instructions in the [ETPM Manual](#) in conjunction with this job aid, to document the condition(s) on an SAP notification.

Fiberglass Guy Strain Insulators

Sources of Ignition

A second source of ignition is present when un-sectionalized guys are attached to the bonding or are in close proximity to the bonding. If this situation occurs, the fault can travel along the guy wire to ground at the anchor, resulting in ignition.

Line events may occur when:

- Trees contact lines
- Broken, damaged, tracking or flashing of insulators
- Hardware is deteriorated or damaged
- Birds contacting structure/guy wire-to-conductor

Fiberglass strain insulators are to be attached at the Structure-end of the Transmission guy. Guy fixtures are to be tied into the Transmission bonding.

Steel poles do not require fiberglass guy insulators unless there is a Distribution under-build.



Storm guy fixtures outside the barrel of proximity and located 10’ or more below the lowest level of Transmission conductors do not require bonding or fiberglass links. This also applies to storm guys located at or below the Distribution level.

The following documents are available to help determine if an LC notification is required:

- Job Aid [TD-1001M-JA13]
- Flow Chart/Cylinder of Proximity

Fiberglass Guy Strain Insulators: Job Aid

- Job Aid [TD1001M-JA13] Identifying Levels of Damage and Condition of Guys and Anchors on Transmission Line Structures and Supports

Guys Condition Levels and Impact	
Condition 1	<div><p>No visible damage</p><p>Action:</p><ol style="list-style-type: none">1. None.2. Take photos.3. Continue monitoring.4. No Priority Code.</div> <div></div> <div></div>


Fiberglass Guy Strain Insulator FDAs

1. Condition
2. FDA
3. FDA
4. Priority - Duration

89


Insulator Flow Chart

- Un-Sectionalized Guy Wires
Decision-Making Tree




Identifying Need for Fiberglass Guy Strain Insulators

Cylinder of Proximity



Damage and Condition of Splices

 Identifying Levels of Damage and Condition of Splices on Transmission Line Structures and Supports		TD-1001M-JA14 Published: 01/20/2023 Effective: 02/20/2023 Rev: 2
PPE: Standard T-Line PPE, including: <ul style="list-style-type: none"> • Hard hat • Safety glasses • Gloves • FR clothing • Safety boots • Fall protection 	Guidance Document References: TD-1001M, Electric Transmission Preventive Maintenance Manual	
	Tools: <ul style="list-style-type: none"> • Binoculars • Camera 	Level of Use: <ul style="list-style-type: none"> <input type="checkbox"/> Information <input checked="" type="checkbox"/> Reference <input type="checkbox"/> Continuous

Purpose:

This job aid provides the steps for consistent identification of splices in transmission lines, evaluation of condition, and consistent decision-making. Splices are also known as sleeves.

The Qualified Company Representative (QCR) should use this guide to identify the splice, confirm proper application, select the appropriate condition representing the location or deterioration level, and consistently assign the priority code.

Follow instructions in the [ETPM Manual](#), in conjunction with this job aid to document the condition(s) on an SAP notification.

Damage and Condition of Splices: Job Aid

- Job Aid [TD1001M-JA14] Identifying Levels of Damage and Condition of Splices on Transmission Line Structures and Supports

Types of Splices (Sleeves):



Automatic Splice



Western Union Splice



Shunt Splice (installed over existing splice)



Twisted Splices



Bolted Splices



Compression Splices



Moused Splices



Splice Condition Levels and Impact

Condition 5

1 Severe damage with an immediate safety concern OR potential to impact operations.

- > 50% material loss

Action:

4

1. Take photos of damage.
2. Choose Priority Code A.

2

40617026

>50% material loss (cracked)
FDA: Emergency | Storm Related | Repair

3

40908948

>50% material loss (burnt)
FDA: Emergency | Storm Related | Repair

NOTE
For hot splices, reference ETPM Job Aid TD-1001M-JA19, "Evaluating Conditions from Infrared (IR) Inspections in Transmission Lines."

1. Condition
2. FDA
3. FDA
4. Priority - Duration

Splice Condition Levels and Impact (continued)

Condition 3

1 Moderate damage with possible longer-term impact to safety, facility integrity, or operations.

- Any visible damage to splice
- Automatic splice
- Any splice < 10 feet to clamp*

***NOTE:** Undamaged splices < 10 feet to clamp are non-threatening. Recommended to mitigate condition within 36 months.

Action:

4

1. Take photos of the damage.
2. Choose Priority Code E.

2

40873623

Automatic splice
FDA: Splice-Wood | No good | Replace


3

44258938

Twist splice < 10' to clamp
FDA: Splice-Wood | No good | Repair

NOTE
For hot splices, reference ETPM Job Aid TD-1001M-JA19, "Evaluating Conditions from Infrared (IR) Inspections in Transmission Lines."

Deterioration and Corrosion of Switches

 Identifying Levels of Deterioration and Corrosion on Transmission Line Switches		TD-1001M-JA15 Published: 01/20/2023 Effective: 02/20/2023 Rev: 2
PPE: Standard T-Line PPE, including: <ul style="list-style-type: none"> • Hard hat • Safety glasses • Class II rubber gloves • FR clothing • Safety boots • Fall protection 	Tools: <ul style="list-style-type: none"> • Binoculars • Camera 	Guidance Document References: TD-1001M, Electric Transmission Preventive Maintenance Manual
		Level of Use: <ul style="list-style-type: none"> <input type="checkbox"/> Information <input checked="" type="checkbox"/> Reference <input type="checkbox"/> Continuous

Purpose:

This job aid provides the steps for consistent evaluation of deterioration and corrosion on transmission line (T-Line) switches. The evaluation classifies the severity and potential impact of the deterioration and/or corrosion and provides the description of each condition level. The Qualified Company Representative (QCR) combines switch condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level.

The QCR should use this guide to select the appropriate condition representing the as-found corrosion level for assigning the recommended priority code. Follow instructions in the [ETPM Manual](#), in conjunction with this job aid, to document the condition(s) on an SAP notification.

Deterioration and Corrosion of Switches: Job Aid

- Job Aid [TD1001M-JA15] Identifying Levels of Deterioration and Corrosion on Transmission Line Switches

Components of Detailed Switch Inspection:

Inspect the items listed below on all switches, as applicable:

- Switch operating name and number: Confirm that these are present.
 - Switch platform and associated grounding:
 - Check condition of bonding connections and/or straps between the platform and operating handle.
 - Check if switch handle is properly connected.
 - Check condition of all ground connections between the operating handle, ground rods, and motor operator (if equipped).
 - Check ground-mounted platforms to ensure that foreign objects do not ground them.
 - Check that platform is secured and properly positioned on supporting piers.
 - Control mechanism:
 - Check if operating handle and control rod are bent or damaged.
 - Check if operating handle mounting bolts are tight and secured.
 - Examine fiberglass control rod for exposed stringy fiber.
 - Insulators:
 - Check insulator units for tracks, flash marks, or contamination.
 - Check that insulator is plumb to the mounting surface.
 - Switch contacts:
 - Check that switch in a fully closed position.
 - Check that switch aligns both vertically and horizontally.
 - Check for unauthorized attachments.
 - Switch attachments:
 - Arcing horns
 - Inspect arcing horns for excessive wear.
 - Check for wear between the stationary pre-strike and rotating blade pre-strike arms.
 - High Speed (Break) Interrupters
 - Check that whip is properly engaged with the catch when the switch is in the closed position.
 - Check condition of the whips (e.g., erosion due to burning or improper installation).
 - Vacuum Interrupters
 - Check that the trip arm and catch arm properly latch when switch is closed.
 - Check for signs of external arcing or cracks.
 - Motor Operator (MO) or Motorized Switch Operator (MSO), batteries, and accessory wiring:
 - Cabinet
 - Check the cabinet for leaks or water intrusion.
 - Ensure that there is no damage from vandalism or third-party contact.
 - Ensure that the ground wire and associated connections are in proper condition.
 - Check the internal components for proper working conditions, wear, corrosion, and tightness.
 - Batteries
 - Visually inspect the battery case for bulging, terminal corrosion, and case leakage.
 - Test batteries to ensure voltage is acceptable, in accordance with the manufacturer's instructions.
 - Replace batteries
 - IF batteries were not replaced, THEN provide explanation.
- Example:** Batteries were replaced within the last 6 months and passed the 3 Volt drop test.

Corrosion and Structure Condition Levels and Impact (continued)

Condition 5 (continued)

1 **Severe damage with an immediate safety concern OR potential to impact operations.**

- > 50% material loss
- Cracked > 50%
- Arcing or evidence of arcing
- Switch operating mechanism unlocked
- Inoperable
- Out of adjustment (blades and load break devices not fully seated)
- Missing/damaged switch attachment*
- Inform GCC that SCADA is not operational (no tag required unless instructed)



***NOTE:** Priority A may be addressed by contacting GCC and marking switch inoperable with a "Caution" tag and repair tag time frame, as appropriate.

4 **Action:**

1. Take photos of damage.
2. Choose Priority Code A.

2 **Switch rod not fully seated**
FDA: Emergency | Storm-Related | Repair

3 **Switch blade not fully seated**
FDA: Emergency | Storm-Related | Repair



1. Condition
2. FDA
3. FDA
4. Priority - Duration

Corrosion and Structure Condition Levels and Impact (continued)

Condition 3

1 **Moderate damage with possible longer-term impact to safety, facility integrity, or operations.**

- 30–50% material loss
- Cracked 5–50%
- Contaminated (heavy)
- Tracking (heavy)
- Loose/broken/missing parts or hardware
- Heating
- Bent/bowed control rod or platform
- Switch handle not bonded to platform*



***NOTE:** For switch handles not bonded to platform, address within 12 months.

4 **Action:**

1. Take photos of damage.
2. Choose Priority Code E.

2 **Missing/covered operating platform**
FDA: Switch-Wood | No Good | Repair

3 **Cracked crossarm and insulator**
FDA: Switch-Wood | No Good | Replace



Anti-Climbing Guards

- Anti-Climbing Guards are installed where tower and lattice steel poles can be easily climbed and is primarily in:
 - Rural: Areas with a population of less than 1,000 persons per square mile as determined by the latest United States census.
 - Urban: Areas with a population of more than 1,000 people per square mile as determined by the latest United States census.
 - Near Roads or Trails: At a short distance. Approximately ¼ mile or 1,320 ft. of frequently traveled roads/trails.
 - Camp: A group of cabins or other shelters used for vacationing, living, or other purposes.
- A suitable barrier shall be installed on towers and lattice steel poles, or other provisions shall be made to prevent easy climbing.
- TD-1009S presents the requirements for evaluating the potential for T&D towers and lattice steel poles for climbing by unauthorized persons, based on structure design, location, access, and local activities.



Anti-Climbing Guard FDA’s

Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Anti-climbing guards are missing	Yes	Marker (i.e. signs)-Steel	Missing	Install

Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Anti-climbing guards are broken, cracked, damaged	Yes	Marker (i.e. signs)-Steel	No Good/Out of Std	Install

Wood Poles & Non-Steel Framing

Job Aid Details:

- Inspection Steps
- Visual Inspection of Physical Defects
- Sound Inspection/Hammer Test
- Evaluation of Intrusive Inspection Results
- Evaluation of Previously-Stubbed Poles



Identifying Levels of Damage and Condition of Wood Poles and Non-Steel Framing on Transmission Line Structures and Supports

TD-1001M-JA06

Published: 01/20/2023

Effective: 02/20/2023

Rev: 3

PPE:

Standard T-Line PPE, including:

- Hard hat
- Safety glasses
- Gloves
- FR clothing
- Safety boots
- Fall protection

Tools:

- Binoculars
- Camera
- Hammer
- Non-conductive ruler

Guidance Document References:

[TD-1001M, "Electric Transmission Preventive Maintenance Manual"](#)

Level of Use:

- ☐ Information
- ☒ Reference
- ☐ Continuous

Purpose:



This job aid provides the steps for consistent evaluation of damage on wood poles and non-steel framing on transmission line (T-Line) structures. The evaluation classifies the severity and potential impact of the damage or deterioration and provides the description of each condition level. The Qualified Company Representative (QCR) combines wood pole and non-steel framing condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level.

The QCR should use this guide to select the appropriate condition representing the as-found damage or deterioration level for assigning the recommended priority code. Follow instructions in the [ETPM Manual](#), in conjunction with this job aid, to document the condition(s) on an SAP notification.

Woodpecker Damage

Job Aid Guide

1. Condition is Listed – 3
2. Recommended FDA Provided
3. Recommended FDA Provided
4. Priority & Duration Provided

Wood Structure Condition Levels and Impact (continued)	
<div style="background-color: yellow; padding: 5px; border: 1px solid black;">Condition 3</div>	<p>Moderate damage with possible longer-term impact to safety, facility integrity, or operations.</p> <ul style="list-style-type: none"> • Burnt/rotten 20–50% material loss • Crossarm bracing loose/missing • Bond wire broken > ¼-inch gap • Pole top damage or split top, compromising hardware or crossarm integrity * • Twisted • H-Frame cross brace broken or missing * • Out of plumb > 3 feet and compromising insulators and conductor * • Slide > 5 feet • Soil movement (erosion > 3 feet in the ground) • Worm/woodpecker/insect damage (severe and/or near hardware) • Standing water (not including seasonal conditions) • Ground molding in poor condition or missing <p>* NOTE: Recommend to address within 3 months.</p> <p>Tags include work on wood poles, crossarms, crossbraces, bonding, bearing plates.</p> <p>Action:</p> <ol style="list-style-type: none"> 1. Take photos of damage. 2. Choose Priority Code E.
	<div style="text-align: right;">1</div>  <p>40907424</p> <p>Medium woodpecker hole at pole top near hardware FDA: Structure-Wood No Good Replace</p>
	<div style="text-align: right;">2</div>  <p>40907440</p> <p>Multiple unconnected woodpecker holes at pole top FDA: Structure-Wood No Good Replace</p>
	<div style="text-align: right;">3</div>
	<div style="text-align: right;">4</div>

CONFIDENTIAL – Provided Pursuant to Confidentiality Declaration (“WMP-Discovery2023-2025_DR_CalAdvocates_046_Delivery 2_Confidentiality Declaration.pdf”)

Wood Structure Condition Levels

Wood Structure Condition Levels and Impact

Condition 5

Severe damage with an immediate safety concern OR potential to impact operations.

- Burnt/rotten > 50% material loss
- Crossarm bracing missing or broken, compromising insulator and conductor
- Bond wire broken < ¼-inch gap
- Severe pole top damage or split top compromising hardware or crossarm integrity
- Cracked (not checks)
- Broken

Tags include work on wood poles, crossarms, crossbraces, bonding, bearing plates.

Action:

1. Take photos of damage.
2. Choose Priority Code A.

Image 1: 40748849
Broken pole top (cracks run across wood grain)
FDA: Emergency | Storm Related | Replace

Image 2: 42574227
Severe woodpecker damage
FDA: Emergency | Storm Related | Replace

1. Condition
2. FDA
3. FDA
4. Priority - Duration

Wood Structure Condition Levels and Impact (continue)

Condition 4

Heavy damage with possible near-term impact to safety, facility integrity, or operations.

- Burnt/rotten 20–50% material loss
- Crossarm bracing loose/missing
- Bond wire broken > ¼-inch gap
- Pole top damage or split top, compromising hardware or crossarm integrity *
- Twisted
- H-Frame cross brace broken or missing *
- Out of plumb > 3 feet and compromising insulators and conductor *
- Slide > 5 feet
- Soil movement (erosion > 3 feet in the ground)
- Worm/woodpecker/insect damage (severe and/or near hardware)
- Standing water (not including seasonal conditions)
- Ground molding in poor condition or missing

* NOTE: Recommend to address within 3 months.

Tags include work on wood poles, crossarms, crossbraces, bonding, bearing plates.

Action:

1. Take photos of damage.
2. Choose Priority Code E.
3. Choose shortened due date (3–12 months) based on conditions and location.

Image 1: 44190964
Multiple large woodpecker holes at pole top
FDA: Structure-Wood | No Good | Replace

Image 2: 44190964
Ruler shows continuous woodpecker cavity
FDA: Structure-Wood | No Good | Replace

Wood Structure Condition Levels and Impact (continued)

Condition 3 (continued)

1 **Moderate damage with possible longer-term impact to safety, facility integrity, or operations.**

- Burnt/rotten 20–50% material loss
- Crossarm bracing loose/missing
- Bond wire broken > ¼-inch gap
- Pole top damage or split top, compromising hardware or crossarm integrity *
- Twisted
- H-Frame cross brace broken or missing *
- Out of plumb > 3 feet and compromising insulators and conductor *
- Slide > 5 feet
- Soil movement (erosion > 3 feet in the ground)
- Worm/woodpecker/insect damage (severe and/or near hardware)
- Standing water (not including seasonal conditions)
- Ground molding in poor condition or missing

*** NOTE:** Recommend to address within 3 months.

Tags include work on wood poles, crossarms, crossbraces, bonding, bearing plates.

4 **Action:**

1. Take photos of damage.
2. Choose Priority Code E.

2 **Split pole top, no anti-split bolt present. Dead-end hardware not slipping.**
FDA: Hardware-Wood | Missing | Install

3 **Pole out of plumb, ~5"**
FDA: Structure-Wood | No Good | Replace

40588392

40758524

1. Condition
2. FDA
3. FDA
4. Priority - Duration

Wood Structure Condition Levels and Impact (continued)

Condition 2

1 **Light damage with no expected near-term impact to facility integrity or operations.**

- Slide 1–5 feet
- Soil movement (erosion 1–3 feet in the ground)
- Worn/woodpecker/insect damage (medium or minor damage near hardware)
- Climbing steps in poor condition

Tags include work on wood poles, crossarms, cross braces, bonding, bearing plates.

4 **Action:**



1. Take photos.
2. Choose Priority Code F.

2 **Medium unconnected woodpecker holes not near hardware**
FDA: Structure-Wood | No Good | Repair



3 **Rotten pole butt. Hole may destabilize the structure.**
FDA: Structure-Wood | Debris | Remove

40904730


40610422

Crossarm Condition Levels and Impact	
<div>Condition 5</div> <div>1</div> <div>Severe damage with an immediate safety concern OR potential to impact operations.<ul style="list-style-type: none">Burnt/rotten > 50% material lossCrossarm bracing missing or broken, compromising insulator and conductorBond wire broken < ¼-inch gapSevere pole top damage or split top compromising hardware or crossarm integrityCracked (not checks)Broken</div> <div>Tags include work on wood poles, crossarms, crossbraces, bonding, bearing plates.</div> <div>Action:<div>4</div><ol style="list-style-type: none">Take photos of damage.Choose Priority Code A.</div>	 <p>Broken crossarm bracing, compromising insulators FDA: Emergency-Wood Other Replace</p> <div>2</div>  <p>Broken crossarm (cracks run across wood grain) FDA: Emergency-Wood Other Replace</p> <div>3</div>

1. Condition
2. FDA
3. FDA
4. Priority - Duration

Crossarm Condition Levels and Impact (continued)	
<div>Condition 4</div> <div>1</div> <div>Heavy damage with possible near-term impact to safety, facility integrity, or operations.<ul style="list-style-type: none">Burnt/rotten 20–50% material lossCrossarm bracing loose/missingBond wire broken > ¼-inch gapPole top damage or split top, compromising hardware or crossarm integrity *TwistedH-Frame cross brace broken or missing *Out of plumb > 3 feet and compromising insulators and conductor *Slide > 5 feetSoil movement (erosion > 3 feet in the ground)Worm/woodpecker/insect damage (severe and/or near hardware)Standing water (not including seasonal conditions)Ground molding in poor condition or missing</div> <div>* NOTE: Recommend to address within 3 months.</div> <div>Tags include work on wood poles, crossarms, crossbraces, bonding, bearing plates.</div> <div>Action:<div>4</div><ol style="list-style-type: none">Take photos of damage.Choose Priority Code E.Choose shortened due date (3–12 months) based on conditions and location.</div>	 <p>Split crossarm compromising hardware FDA: Crossarm-Wood No good Replace</p> <div>2</div>  <p>Broken H-frame cross brace FDA: Crossarm-Wood No good Replace</p> <div>3</div>

Evaluating Conditions for Vegetation

 Evaluating Conditions for Vegetation Nonconformances in Transmission Lines		TD-1001M-JA20 Published: 01/20/2023 Effective: 02/20/2023 Rev: 1
PPE: Standard T-Line PPE, including <ul style="list-style-type: none"> • Hard hat • Safety glasses • Gloves • FR clothing 	Tools: <ul style="list-style-type: none"> • Camera 	Guidance Document References: TD-1001M, "Electric Transmission Preventive Maintenance Manual"
		Level of Use: <ul style="list-style-type: none"> <input type="checkbox"/> Information <input checked="" type="checkbox"/> Reference <input type="checkbox"/> Continuous
Purpose: This job aid provides the instructions and requirements for routine inspection of vegetation around PG&E electric transmission lines to ensure the safe and reliable operation of facilities.		

Vegetation Conditions

There are two types of vegetation conditions requiring action:

Steel Structure

- Vegetation impacting Structure, Framing or Lines
- Significant woody vegetation around Concrete Foundation

Non-Steel Structure

- Vegetation impacting Structure, Framing or Lines
- Significant woody vegetation around Base

Vegetation Conditions

When looking at Vegetation-to-Conductor clearance distances, including De-energized components, refer to Table 1 below.

Table1: Vegetation-to-Conductor Clearance Distance

Voltage (kV)	Clearance Distance	Action Required
60/70*	4 feet or less	Call VPM (Veg Program Manager)
115*	10 feet or less	Call VPM
230	10 feet or less	Call GCC and VPM
500	15 feet or less	Call GCC and VPM

* If the line is NERC/CAISO critical (Spaulding – Summit 60kV, Drum-Summit #1 115kV and Drum-Summit #2 115kV), call the GCC and VPM as required for 230kV and 500kV lines.

Vegetation Conditions

If woody vegetation is in contact with the pole or tower, vegetation is impacting the structure (including the guy) or significantly interferes with the inspection of the pole or structure base or footings:

1. Document the observation in the Inspection Checklist
2. Create a notification for Vegetation Removal with the FDA code noted below. Choose the appropriate Priority Code for the situation, then Vegetation Management will arrange for appropriate vegetation work.

Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Woody vegetation is in contact with the pole or tower, vegetation is impacting the structure (including the guy) or significantly interferes with the inspection of the pole or structure	Yes	Vegetation	Overgrown	Remove
Woody vegetation is in contact with the pole or tower, vegetation is impacting the structure (including the guy) or significantly interferes with the inspection of the pole or structure	Yes	Vegetation-Tower	Overgrown	Cage Clearing

Vegetation Management

IF THERE IS **AN IMMINENT THREAT** AS DEFINED BELOW, there are additional immediate communications required.

Imminent Threat Scenario: Vegetation-to-Conductor Clearance Distance

- tree uprooting
- tree leaning towards lines or structures
- tree approaching Imminent Threat Vegetation-to-Conductor Clearance Distance which could be compromised by line sag or sway.

Table 2: Imminent Threat Vegetation-to-Conductor Clearance Distance

Voltage (kV)	Clearance Distance	Action Required
60/70*	1' 4" or less	Call your PG&E Lead
115*	2' 4" or less	Call your PG&E Lead
230	4' 7" or less	Call your PG&E Lead
500	8' 3" or less	Call your PG&E Lead


*If the line is NERC/CAISO critical (Spaulding –Summit 60kV, Drum-Summit #1 115kV and Drum-Summit #2 115kV), call the GCC and VPM as required for 230kV and 500kV lines.

Vegetation Management - Condition 5

Job Aid [TD-1001M-JA20] Evaluating Conditions for Vegetation Nonconformances in Transmission Lines

Job Aid Guide:

1. Condition is Listed – 5
2. Recommended FDA Provided
3. Recommended FDA Provided
4. Priority Provided

Vegetation Condition Levels and Impact	
Condition 5	<p>1 Tree contacting line or showing signs of contact (burnt leaves or limbs)</p> <p>Action:</p> <p>4 Priority Code A.</p> <p>2. Take pictures of damage.</p>
	 <p>2 Tree fell across line FDA: Emergency Storm Related Repair</p>
	 <p>3 Tree contacting conductors FDA: Emergency Storm Related Repair</p>

[Refer to Job Aid TD-1001M-JA20]

CONFIDENTIAL – Provided Pursuant to Confidentiality Declaration (“WMP-Discovery2023-2025_DR_CalAdvocates_046_Delivery 2_Confidentiality Declaration.pdf”)

Vegetation Management - Condition 3 & 4


Vegetation Condition Levels and Impact (continued)

Condition 3

1 Significant woody vegetation around base of structure, impacting climbing and/or visual inspection of base of structure


4 Action:

1. Priority Code E.
2. Take pictures of damage.



40856946

2 Woody brush obstructing inspection
FDA: Vegetation | Overgrown | Remove



40667890

3 Trees and brush at base of pole, blocking pole access/climbing
FDA: Vegetation | Overgrown | Remove

1. Condition
2. FDA
3. FDA
4. Priority - Duration


Vegetation Condition Levels and Impact (continued)

Condition 4

1 Tree clearance < G.O. 95 or PG&E-required
Clearances < G.O. 95


Action:

1. Take pictures of damage.
2. Select Priority Code E.
3. Choose shortened due date (3–12 months) based on conditions and location.



40648278

2 Tree clearance < G.O.95
FDA: Vegetation | Overgrown | Remove



40598760

3 Dead tree in proximity to line: tree height is greater than distance to line
FDA: Vegetation | Overgrown | Remove

Knowledge Check

Let's review:

Which of these situations require an LC Notification? Priority?

- A. 1
- B. 2
- C. 3



1



2



3

Knowledge Check - Answers

Let's review:

Which of these situations require an LC Notification? Priority?

- A. 1 - LC Notification, Priority A
- B. 2 – No LC Required
- C. 3 - LC Notification, Priority E



1





2



3

Identifying Conductor and Insulator Conditions Job Aids

 Identifying Conductor and Clearance Conditions		TD-1001M-JA10 Published: 01/20/2023 Effective: 02/20/2023 Rev: 3
PPE: Standard T-Line PPE, including: <ul style="list-style-type: none"> • Hard hat • Safety glasses • Gloves • FR clothing 	Guidance Document References: TD-1001M, <i>Electric Transmission Preventive Maintenance Manual</i>	
	Tools: <ul style="list-style-type: none"> • Binoculars • Camera 	 Identifying Levels of Corrosion and Condition of Hardware and Insulators on Transmission Line Structures and Supports
		TD-1001M-JA07 Published: 01/20/2023 Effective: 02/20/2023 Rev: 4

Purpose:

This job aid provides the steps for consistent evaluation of conductor and insulator conditions. The evaluation classifies the severity and potential impact of the rust, corrosion, or deterioration, and provides the description of each condition level. The Qualified Company Representative (QCR) combines hardware or insulator condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level.

The QCR should use this guide to select the appropriate condition representing the as-found corrosion or deterioration level for assigning the recommended priority code. Follow instructions in the [ETPM Manual](#), in conjunction with this guide, to document the condition(s) on an SAP notification.

PPE: Standard T-Line PPE, including: <ul style="list-style-type: none"> • Hard hat • Safety glasses • Gloves • FR clothing • Safety boots • Fall protection 	Tools: <ul style="list-style-type: none"> • Binoculars • Camera 	Guidance Document References: TD-1001M, “<i>Electric Transmission Preventive Maintenance Manual</i>”
		Level of Use: <ul style="list-style-type: none"> <input type="checkbox"/> Information <input checked="" type="checkbox"/> Reference <input type="checkbox"/> Continuous

Purpose:

This job aid provides steps for consistent evaluation of rust and corrosion on hardware and insulators on transmission line (T-Line) structures. The evaluation classifies the severity and potential impact of the rust, corrosion, or deterioration, and provides the description of each condition level. The Qualified Company Representative (QCR) combines hardware or insulator condition with other as-found conditions and risk factors to assess and recommend the appropriate priority level.

The QCR must use this guide to select the appropriate condition representing the as-found corrosion or deterioration level for assigning the recommended priority code. Follow instructions in the [ETPM Manual](#), in conjunction with this guide, to document the condition(s) on an SAP notification.


Conductor: Conditions

The *Identifying Conductor Conditions Job Aid [TD-1001M-JA10]* is available to provide consistency to assess if notifications need to be created, condition codes and priority codes.

EXAMPLES:



Severe Bird Caging near connector, Condition 5, Priority A



Slipped Strand / Loose Messenger, Condition 3, Priority E



Pollutants But No Loss of Material, Condition 1, No Notification Required

Conductor: Clearances

Minimum Conductor Clearance Tables

Table 1. Minimum Conductor-to-Ground Clearance Calculations

Voltage	60, 70, 115 kV	60, 70, 115 kV (over railroad)	230 kV	230 kV (over railroad)	500 kV	500 kV (over railroad)
Minimum Clearance Requirement	30 feet ¹	34 feet ¹	30 feet ¹	34 feet ¹	35 feet ¹	39 feet ¹

¹ **Note:** If the measured conductor-to-ground clearance is less than shown on this table, consult transmission line engineering to determine the optimal conductor-to-ground clearance for the location in question and whether remediation is required.

Clearances must be measured at the low point in the span. Across uneven terrain, this might not be at the mid-span. See [Figure 1, “Clearance Checks on Uneven Terrain”](#) on Page 3.

Table 2. Minimum Conductor-to-Conductor (Circuit-to-Circuit) Clearances

Voltage	60/70 kV	115 kV (Wood)	115 kV (Non Wood)
Minimum Separation for Circuits Supported on Same Structure	48 inches	84 inches	120 inches
Minimum Separation to Distribution on an Interset Pole	96 inches	120 inches	120 inches

A Job Aid [TD-1001M-JA10] is available showing these distances, along with guidance on how to measure the clearances.

Phase Clearances



Table 2. Minimum Conductor-to-Conductor (Circuit-to-Circuit) Clearances

Voltage	60/70 kV	115 kV (Wood)	115 kV (Non Wood)
Minimum Separation for Circuits Supported on Same Structure	48 inches	84 inches	120 inches
Minimum Separation to Distribution on an Interset Pole	96 inches	120 inches	120 inches



Missing cotter key backed out pin



Insulator - Guide for Replacing Damaged Insulators

Job Aid [JA07] is available showing these numbers, along with guidance on how to determine if an LC notification is required

Table 2

Voltage	Configuration	Contamination District	G.O. 95 Minimum Requirements		Design # of Units	Minimum # of Units
			Dry Flashover	# of Units		
500 kV	Dead-end	AAA	1,190 kV	23	34	32
	Dead-end	B, C, D			34	32
	Vee String	AAA			36	34
	Vee String	B, C, D			34	32
	Suspension	AAA			32	30
	Suspension	B, C, D			32	30
230 kV	Dead-end	AAA	582 kV	12	24	20
	Dead-end	A			24	20
	Dead-end	B, C, D			15	13
	Suspension	AAA			15	13
	Suspension	A, B, C, D			15	13
115 kV	Dead-end	AAA	333 kV	6	12	10
	Dead-end	A			11	9
	Dead-end	B			10	8
	Dead-end	C, D			9	8
	Suspension	AAA			10	6
	Suspension	A, B			8, 9	6
	Suspension	C, D			8	6
60/70 kV	Dead-end	AAA	180 kV	3	7	5
	Dead-end	A, B			6	5
	Dead-end	C, D			5	5
	Suspension	AAA, A, B			5	3
	Suspension	C, D			4	3

CONFIDENTIAL – Provided Pursuant to Confidentiality Declaration (“WMP-Discovery2023-2025_DR_CalAdvocates_046_Delivery 2_Confidentiality Declaration.pdf”)

Conductor & Insulator FDAs

Conductor Condition Levels and Impact (continued)

Condition 3

1 Moderate damage or moderate corrosion with possible longer-term impact to safety, facility integrity, or operations.


- 10–50% material loss
- Broken strands and out-of-lay strands (e.g., gunshot), 5–40%; see [Numbered Document 028855](#)

4 Evidence of arcing (recommended to complete within 3 months)

- Broken or loose tie wire (conductor well seated in the saddle with vertical load or partially captured with tie wire)
- Broken ground wire
- Loose connector or weight
- Twisted bundled conductor (recommended to complete within 3 months)
- Conductor kinked/pinched at clamp
- Vibrating (send to engineering personnel for evaluation)
- Ground wire in poor condition (corrosion, flashed, missing)


4 Action:

1. Take pictures of the damage.
2. Choose Priority Code E.



41123857

2 ~25-30% strands broken
FDA: Conductor-Wood | No good | Repair



40738079

3 Loose tie wire, conductor well seated
FDA: Tie Wire-Wood | No good | Replace

1. Condition
2. FDA
3. FDA
4. Priority - Duration

Insulator Condition Levels and Impact (continued)


Condition 5 (continued)

1 Severe deterioration with an immediate safety concern OR potential to impact operations.

- > 50% material loss
- Contaminated (arcing)


Action:

- 4** 1. Take photos of the damage.
2. Choose Priority Code A.



40875900

2 >50% material loss on insulator pin
FDA: Emergency-Steel | Other | Replace



40649241

3 >50% material loss on insulator pin
FDA: Emergency-Steel | Other | Replace


Insulator: Divide-Vandenberg #1 4/35

Example #1: **Emergency Priority - A**



Insulator: Divide-Vandenberg #1 4/35 (continued)

Example # 2: **Emergency Priority - A**



Knowledge Check

Let's review:

Using the Table, Which of the following situations require an LC Notification? What Priority?

- A. A 230kV dead-end insulator string, Contamination District B, has 20 bells total with 4 broken
- B. A 115kV suspension insulator string, Contamination District B, has 9 bells total with 4 broken

Voltage	Configuration	Contamination District	G.O. 95 Minimum Requirements		Design # of Units	Minimum # of Units
			Dry Flashover	# of Units		
500 kV	Dead-end	AAA	1,190 kV	23	34	32
	Dead-end	B, C, D			34	32
	Vee String	AAA			36	34
	Vee String	B, C, D			34	32
	Suspension	AAA			32	30
	Suspension	B, C, D			32	30
230 kV	Dead-end	AAA	582 kV	12	24	20
	Dead-end	A			24	20
	Dead-end	B, C, D			15	13
	Suspension	AAA			15	13
	Suspension	A, B, C, D			15	13
115 kV	Dead-end	AAA	333 kV	6	12	10
	Dead-end	A			11	9
	Dead-end	B			10	8
	Dead-end	C, D			9	8
	Suspension	AAA			10	6
	Suspension	A, B			8, 9	6
	Suspension	C, D			8	6
60/70 kV	Dead-end	AAA	180 kV	3	7	5
	Dead-end	A, B			6	5
	Dead-end	C, D			5	5
	Suspension	AAA, A, B			5	3
	Suspension	C, D			4	3

Knowledge Check - Answers

Let's review:

Using the Table, Which of the following situations require an LC Notification? What Priority?

- A. A 230kV dead-end insulator string, Contamination District B, has 20 bells total with 4 broken
 This is not an urgent situation. It should be noted in the inspection form, but it does not need immediate attention.
- B. A 115kV suspension insulator string, Contamination District B, has 9 bells total with 4 broken
 This is a Priority-**E** situation because it is LESS than the minimum number of insulators required. Call your PG&E Lead.

Voltage	Configuration	Contamination District	G.O. 95 Minimum Requirements		Design # of Units	Minimum # of Units
			Dry Flashover	# of Units		
500 kV	Dead-end	AAA	1,190 kV	23	34	32
	Dead-end	B, C, D			34	32
	Vee String	AAA			36	34
	Vee String	B, C, D			34	32
	Suspension	AAA			32	30
	Suspension	B, C, D			32	30
230 kV	Dead-end	AAA	582 kV	12	24	20
	Dead-end	A			24	20
	Dead-end	B, C, D			15	13
	Suspension	AAA			15	13
	Suspension	A, B, C, D			15	13
115 kV	Dead-end	AAA	333 kV	6	12	10
	Dead-end	A			11	9
	Dead-end	B			10	8
	Dead-end	C, D			9	8
	Suspension	AAA			10	6
	Suspension	A, B			8, 9	6
	Suspension	C, D			8	6
	Suspension	C, D			8	6
60/70 kV	Dead-end	AAA	180 kV	3	7	5
	Dead-end	A, B			6	5
	Dead-end	C, D			5	5
	Suspension	AAA, A, B			5	3
	Suspension	C, D			4	3

Knowledge Check

Let’s review:

Using Table 4 below, which of the following scenarios would require an Emergency Priority-A** Notification?**

- A. Insulator rust shows greater than 50% material loss
- B. Insulator showing medium tracking
- C. Insulator worn greater than 50% material loss
- D. Insulator cracked to the cap

Component	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Insulator (INSU) Insulator-Steel (INSS) Insulator-Wood (INSW) Note: For insulators that are flashed, cracked, broken, gunshot, or chipped > 1-1/2 inches, see Job Aid TD-1001M-JA07 .	<ul style="list-style-type: none"> > 50% Material loss Contaminated (arcing) 	<ul style="list-style-type: none"> 30–50% Material loss Contaminated (heavy) Tracking (heavy) Missing/loose cotter key in retainer pin Out-of-plumb, post or suspension insulator, exhibiting signs of impacting conductor Chalking/cracking on polymer Corona rings damaged, missing (where required), or improperly installed (500 kilovolt [kV] only) 	<ul style="list-style-type: none"> Contaminated (medium) Tracking (medium) Out-of-plumb post insulator > 6 inches

Knowledge Check

Let’s review:

Using Table 4 below, which of the following scenarios would require an Emergency Priority-A** Notification?**

- A. Insulator rust shows greater than 50% material loss
- B. Insulator showing medium tracking
- C. Insulator worn greater than 50% material loss
- D. Insulator cracked to the cap

Component	Priority Code		
	A (Level 1 – Immediate)	E (Level 2 – 6/12/36 Months)	F (Level 3 – 60 Months)
Insulator (INSU) Insulator-Steel (INSS) Insulator-Wood (INSW) Note: For insulators that are flashed, cracked, broken, gunshot, or chipped > 1-1/2 inches, see Job Aid TD-1001M-JA07 .	<ul style="list-style-type: none"> > 50% Material loss Contaminated (arcing) 	<ul style="list-style-type: none"> 30–50% Material loss Contaminated (heavy) Tracking (heavy) Missing/loose cotter key in retainer pin Out-of-plumb, post or suspension insulator, exhibiting signs of impacting conductor Chalking/cracking on polymer Corona rings damaged, missing (where required), or improperly installed (500 kilovolt [kV] only) 	<ul style="list-style-type: none"> Contaminated (medium) Tracking (medium) Out-of-plumb post insulator > 6 inches

Right-of-Way & Encroachments

Right-of-Way and Encroachments, Attachment 1

Utility Standard: TD-1005S
Publication Date: 12/17/2014 Rev. 0

Permissible Uses of Pacific Gas and Electric Company (Company) Easements

1. Agriculture

Agricultural use of a right-of-way is permissible, provided the use does not prevent access to transmission line facilities at any time. Also, the height of any object in the easement, including the height of standing crops, is limited to 6 feet (ft) above the ground.

2. Automobile Parking

Short-term parking of moveable passenger vehicles and light trucks (pickups, vans, etc.) is allowed, provided heavy equipment access to Company facilities is maintained at all times. Vehicles must not be parked closer than 10 ft to structures. Protection of Company facilities from vehicular traffic must be provided at the developer's expense in accordance with Company specifications. Vehicles on blocks and carports, canopies, or awnings are not allowed.

3. Buildings and Other Structures

Right-of-Way & Encroachments

<p>Right-of-Way and Encroachments, Attachment 1</p>	<p>Utility Standard: TD-1005S Publication Date: 12/17/2014 Rev. 0</p>
<p>Permissible Uses of Pacific Gas and Electric Company (Company) Easements</p>	
<p>1. Agriculture</p> <p>Agricultural use of a right-of-way is permissible, provided the use does not prevent access to transmission line facilities at any time. Also, the height of any object in the easement, including the height of standing crops, is limited to 6 feet (ft) above the ground.</p>	
<p>2. Automobile Parking</p> <p>Short-term parking of moveable passenger vehicles and light trucks (pickups, vans, etc.) is allowed, provided heavy equipment access to Company facilities is maintained at all times. Vehicles must not be parked closer than 10 ft to structures. Protection of Company facilities from vehicular traffic must be provided at the developer's expense in accordance with Company specifications. Vehicles on blocks and carports, canopies, or awnings are not allowed.</p>	
<p>3. Buildings and Other Structures</p> <p>Buildings, swimming pools, wells, or similar structures are not permitted within easements. The Company expressly prohibits the construction of buildings and other structures on transmission facility easements and intends to keep rights-of-way clear of all buildings and structures that might have an adverse effect on Company facilities. Adverse effects include causing a facility to fail, causing mechanical damage to a facility, preventing access to a facility, violating laws and regulations, and creating risks to the public.</p> <p>Exception: Buildings housing the equipment of authorized third parties may be sited on Company easements subject to complete and ongoing review by the Company personnel responsible for land rights and for transmission maintenance, construction, engineering; and asset strategy.</p>	
<p>4. Grading</p> <p>Cuts, trenches, or excavations are not allowed within 25 ft of any tower structure. Proposed grade changes in the vicinity of towers must be reviewed by Company engineers. Fills that impair conductor-to-ground clearances are not allowed. Fills to a clearance of less than 32 feet under lines and near structures must be reviewed to ensure that no clearance impairments occur. Towers must not be left on mounds without adequate road access to the base of the tower or structure. Trenches installed for conduit must be at least 30 inches (in.) below the grade, and the edges of the trenches must be at least 48 in. away from the surface of Company structures at grade level.</p>	
<p>5. Fencing</p> <p>Heavy equipment access to Company facilities must be maintained at all times. Metal fences must be grounded in accordance with Company specifications. Fences located within the footprint of tower footings must be at least 10 ft from the exterior edge of any of the footings. Fences located within the footprint of the tower itself must be at least 2 ft from any face of the tower. If a fence or trellis is running parallel to the transmission line, the owner must provide adequate measures to mitigate induction effects. Proposals for retaining walls or sound walls require Company review.</p>	

Using Standards/Job Aids and Examining Photos

- Is there a threat of potential damage to facilities that could cause an immediate danger?
Contact your PG&E Lead immediately.
- Determine if there is interference and whether permanent access can be maintained.
- Confirm there is sufficient conductor-to-ground clearance, radial line clearances, and clearances around structures.
- Confirm whether excavation, grading, equipment use, or land erosion is impacting pole or tower stability

Examples: Right-of-Way (ROW) – Encroachments


Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Any items around a Structure: Encroachments or other uses on PG&E property or easements, evaluate for interference with maintaining, operating or constructing electric transmission	Yes	Right-of-way	Encroachment	Remove



Example: Right-of-way (ROW) – Well Under Conductor



Examples: Right-of-Way (ROW) – Building or Structure



Right-of-way (ROW): Pools, Buildings, and Structures

Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Any of the below items under conductors: <ul style="list-style-type: none">• Wells• Buildings• Structures• Swimming Pools	Yes	Right-of-way	Encroachment	Remove

Exceptions:

- Buildings that house the equipment of third-parties subject to on-going reviews (e.g., cell tower sites)
- Dirt spoils and stored material, unless CPUC GO95 infraction

Removal of Metal Fence Attachments



Removal of Metal Fence Attachments

Finding	Line Corrective (LC) Notification	Facility	Damage	Action
Unauthorized attachment	Yes	Structure-Steel	Debris, Nest, etc.	Remove
Unauthorized attachment	Yes	Structure-Wood	Debris, Nest, etc.	Remove

Notes:

- Structure-Steel includes lattice steel tower (LST), lattice steel pole (LSP), and tubular steel pole (TSP) Structure-Wood includes wood pole, light duty steel pole (LDSP), fiberglass pole, concrete pole

Requirements:

- You are required to provide recommendations for action
- You are required to add field comments, a map screenshot and two field photos of the condition(s)



Corrective Work on Access Routes

The following serves as a guide to inform on the creation of Electric Transmission Line Corrective work notifications relating to poor, damaged or otherwise neglected access roads.

These are known as **TLR Notifications**

Opportunities -

- Access is not being looked at in conjunction when other corrective work notifications are being created.
 - Example – Is access going to impair the completion of related M&C operations
- Inform on how to create Transmission Line Road (TLR) corrective work notifications
- Educate regarding Work Types as it relates to Transmission Line Road Notifications






Corrective Work on Access Routes

Foundational Knowledge

- PG&E Access Roads are mapped and managed by the Access Roads Team within the Natural Resource Management Group
- Mobile applications such as Maps+, Construct or Inspect applications provide access road specific data that should be an input into creating access related notifications
- At this time, there is no proactive road maintenance program or funding within PG&E to allow for such work
- Road data is updated from within the Access Roads Management team and routinely pushed to the enterprise




Snapshot shown from construct application where access road data is pushed at a routine cadence.

Road specific information can be utilized by selecting the road asset. See next slide.



Corrective Work on Access Routes

Foundational Knowledge




Segment ID – A unique road segment ID for every PG&E access road inventoried

Vehicle Type – Denotes intended vehicle use of road. Does not denote current condition.



Corrective Work on Access Routes

PG&E Road Management Templates shown below





Corrective Work on Access Routes

FDA – Facility; Damage; Action

Facility – Access Road (includes roads, trails, gates and culverts)

Damage – Use Corrective Work Form

Action – Access group will review and prescribe action

After updating Corrective Work Form, the matrix for Access work will look something like:

Select an FDA

Select Facility (required)

Road

Select Damage (required)

Brush Fuel

Encroachments

Grade Change

Missing

No Good/Out of Std

Repair = Expense work
Replace/Reclaim/Install =
Capital work

Expense = MAT - CHS
Capital = MAT - 71Y





Corrective Work on Access Routes

Access related work falls into the following categories:


- **Vegetation clearing** – road is overgrown, or vegetation is restricting, so road needs to be “brushed”= **Expense**
- **Road work Maintenance**– Can be a range of issues; Surface blading, improving road compaction, stabilizing erosion, boulders blocking access, etc. = **Expense**
- **Watercourse crossings** - (e.g., culverts and bridges) unsafe or otherwise not functioning. Can range between install, replace or repair.
 - Replace/Install – Capital
 - Repair existing - Expense
- **Gates** – existing gate is broken or damaged, gate has been stolen or there isn’t a gate, and one is needed.
 - Repair/Broken/Damaged – Expense
 - Missing/Install - Capital
- **NEW Road Reclamation** – If road has clearly not been maintained for 15 or more years and degraded to a condition where the access to our facilities is a reclamation effort, denote as such – **Capital**
 - **Indications of this is limited visibility of past road prism (See slide 9). Road Prism lost or fully impacted by rocks and/or vegetation**

The following examples will provide some general guidance on how to complete the Corrective Work Form to identify access issues for roads or trails.



Corrective Work on Access Routes

Use [Road - Brush/Fuel – Remove] for roads and trails impacted by overgrown vegetation- Expense



*Road Prism clearly visible, Vegetation restricting access
– Include Field note: “Remove vegetation along access
road to pole/tower XX/XX”*



Corrective Work on Access Routes

ROAD WORK: There are many different types of road work *Damage*, and associated *Actions*.



+

Repair = Expense work

Replace, Reclaim = Capital work

Road

×

Select Damage (required)

No Good/Out of Stdrd

×

Select Action (required)

Repair

×

Set Priority (required)

E

×

=



Once TLR notification is created, the access group will review and prepare the *Action*, bring the job through planning, implement and control work to improve access.



Corrective Work on Access Routes

Hardsurfacing treatments – Capital (71Y)

Hardsurfacing (gravel, rock, pavement or other forms of hardening surface – Must be in excess of 714 linear feet OR 10,000 sq ft.





Corrective Work on Access Routes

CULVERT: Where a crossing is plugged or damaged use repair (Expense) – For replacement or failed watercourse crossings (Capital). If we need a new crossing, culvert bridge or other use Culvert – Missing, Install. (Capital)

Repair/Remove = Expense work

Replace/Install = Capital work

Replace Culvert:



Repair Culvert:



Install Crossing:





Corrective Work on Access Routes

GATE:

- If gate is missing (stolen) or we need a new gate use Missing – Install; Capital
- If gate is broken or damaged use Broken/Damaged – Repair, if salvageable; use Replace if gate is beyond repair. These are examples for Expense



Green gate smashed and ripped off hinges – Replace



Corrective Work on Access Routes

There is no road or trail, and one is needed:

Select Facility (required)

Road



Select Damage (required)

Missing




Select Action (required)

Install



NOTE: There is likely a reason there is not a road to this location, thus there is a high likelihood a road is not feasible. Thus, a delete flag may ensue once the land consultant performs their evaluation.

Please use *Field Comments* to indicate type of vehicle for which access is needed – Bucket truck; Pickup; OHV; Foot trail.



Example: Need a foot trail to get to structure for inspection; check the box and make note



Corrective Work on Access Routes

☒ No Road Access, Reclaim – Capital (71Y) Here you need a road for vehicle access, access road missing, check box and make note in *Field Comments*. Road group will visit site and develop prescription for action.





Corrective Work on Access Routes

Additional Information:

Field Comments/Long Text – Provide detail into the issue and request as much as possible. Note operational specifics as needed and/or provide details as you can about the access issue or request.

Encroachment – These are not TLR notifications - ETMP guidance will provide additional information about structural encroachments impeding access, USE - TLS.

Where road is blocked by encroachment (building, Fence, etc.) of any sort check this box; defer to encroachment guidance documents.

Limitations – Be aware of fly in or inaccessible tower locations exist throughout the service territory that access roads can not or will never be built to. Do not create notifications for fly in only locations.

*These are not PGE roads – Access roads are typically Private or Agency (USFS) roads that PGE has an easement allowing access to its facilities. Landowner or Agency may not allow work as prescribed in Notification.



Distribution Conditions

Distribution Conditions

During an Inspection, you may find a **Distribution Condition**.


- You will document the condition by answering the Checklist questions, then create a new LC to report the condition.
- The LC shall include Photos and Comments about the observed condition(s).
- Types of conditions include:
 - Damaged or broken poles
 - Broken or decayed crossarms
 - Broken insulators
 - Damaged tie wire
 - Vegetation issues
 - Missing or broken bridging wire


While traveling to and from inspection locations:

- You have a Duty to Act if you observe a hazard and/or emergency on any of PG&E’s assets, Transmission or Distribution.
- If you observe an immediate hazard and/or emergency, contact your PG&E Lead and standby, if needed.



Example: Distribution Conditions





Cannot Get In (CGI) Overview

Cannot Get In (CGI)

A CGI is identified when an Inspection location is known, but access to the facility prohibits the Inspector from performing an Inspection.

➤ Customer-related Issues:

- Locked Gate
- Bad Dog
- Customer requests to be notified first
- Angry/threatening Customer

➤ Non-Customer Issues:

- Environmental
- Permitting
- Vegetation

CGI – Customer Issues

Finding	LC Notification	Facility	Damage	Action
Locked Gate/Bad Dogs	Yes	Other	Customer Issue	Access Issue
Customer requests to be notified first	Yes	Other	Customer Issue	Appointment Required
Angry or Threatening Customer	Yes	Other	Customer Issue	Customer Refusal

- Facility is behind a locked gate
- Facility has an unleashed dog that poses a safety issue
- Facility is within a secured compound such as Government or Business properties that are fenced and require an appointment
- Facility has property owners that require access negotiation



CGI – Non-Customer Issues

Finding	LC Notification	Facility	Damage	Action
Land/Environmental Issue	Yes	Other	Land/Enviro Issue	Access Issue
Permit required to gain Access	Yes	Other	Permit Required	Access Issue
Dense Vegetation	Yes	Other	Vegetation Overgrown	Access Issue

- Facility is flooded / snow-pack (flooded agriculture, winter/spring storms, etc.)
- Facility requires a Permit to gain access to structure
- Facility is surrounded by overgrown vegetation



Knowledge Check

Let's review:

What does CGI mean?

- A. Conductor Guy Insulator
- B. Customer Gone or Inside
- C. Cannot Get In
- D. Call General Information

Knowledge Check - Answers

Let's review:

What does CGI mean?

- A. Conductor Guy Insulator
- B. Customer Gone or Inside
- C. **Cannot Get In**
- D. Call General Information

Knowledge Check

Let's review:

What are the things you can do to gain access?

- A. Call Customer Service to get gate-code or customer name/phone
- B. Use Inspect App to find Customer gate-code, phone number or access instructions
- C. Talk to local yard or call PG&E Lead to get access information from experience
- D. Create an LC Notification
- E. All the above

Knowledge Check - Answers

Let's review:

What are the things you can do to gain access?

- A. Call Customer Service to get gate-code or customer name/phone
- B. Use Inspect App to find Customer gate-code, phone number or access instructions
- C. Talk to local yard or call PG&E Lead to get access information from experience
- D. Create an LC Notification
- E. All the above



Emergency Priority-**A** Notifications

Emergency Priority-**A** Notification: Imminent Threat

You are required to immediately report any Emergency Priority-**A** condition(s) to the PG&E IRS & Contractor GF. If the PG&E IRS or GF is unavailable, contact your PG&E Construction Manager (CM) and PG&E Supervisor.

If instructed to do so, create an LC notification Priority-**A** and perform the following:

- You are required to stand by until relieved or advised by your PG&E Lead.
- Take action to make the situation safe.
- Take two field photos of the Emergency Priority-**A** condition and location.
- Confirm that the submission is transmitted.

Immediately report the issue to your PG&E Lead

Imminent Threat: Emergency Priority-A Example



Imminent Threat: Emergency Priority-**A** Examples



Knowledge Check

Let's review:

What are the considerations for determining imminent threats?

- A. The risk of exposure to the public, workers, or employees
- B. The abnormality encountered
- C. Risks if the condition continues to deteriorate
- D. Potential for the condition to further deteriorate
- E. Impact of failure to system reliability, customers, and service, and/or the potential for injury
- F. All the above

Knowledge Check - Answers

Let's review:

What are the considerations for determining imminent threats?

- A. The risk of exposure to the public, workers, or employees
- B. The abnormality encountered
- C. Risks if the condition continues to deteriorate
- D. Potential for the condition to further deteriorate
- E. Impact of failure to system reliability, customers, and service, and/or the potential for injury
- F. **All the above**



Pending LC Validation Workflow

Pending LC Field Validation

Requirements

1. Inspector must:
 - Be at the location of the facility being inspected
 - Review the notification information against the location’s current field conditions
 - Document the current field conditions by updating or canceling the LC Notification

2. Tools for documenting the results of the field validation:
 - Inspect App:
 - The Inspect App will display an LC Notification, including photos
 - Within the checklist, identify an existing LC
 - The Inspect App allows an Inspector to enter comments, recommend Priority, document actual field condition(s), and add required photos



FSR Workflow

Field Safety Reassessments


1. A Field Safety Reassessment is intended to cross check the open corrective work on an asset that is in a T2/T3 HFTD and could deteriorate over time.
2. The Compliance Inspector must:
 - ☐ Be at the location of the facility being inspected
 - ☐ Review the notification information against the location's current field conditions
 - ☐ Document the current field conditions by updating or canceling the LC Notification
3. Tools for documenting the results of the field validation
 - ☐ Excel
 - ☐ Inspect App

Field Safety Reassessments


Overall Process

1. **Excel:** Refer to the excel spreadsheet to identify the asset location.

2. **Inspect App:** Look for LC Flag



or Search Notification Number



3. **Inspect App:** Review notification FDAs, Due Date, Priority, Photos, Comments

Field Safety Reassessments

	Field Condition	LC Process	Actions
1	Field Conditions have changed Emergency	Update	<ol style="list-style-type: none"> 1. Follow Emergency Process and Create Priority-A Notification 2. Select Emergency and follow the instructions 3. Update Pending LC: <ol style="list-style-type: none"> a) Enter New Notification Number, Enter Detailed Comments, Attach 2 photos 4. Stand by until relieved
2	Field Conditions have changed Expedite to Priority A	Update	<ol style="list-style-type: none"> 1. Select Expedite to Priority A 2. Update Pending LC <ol style="list-style-type: none"> a) Select a recommended due date, Enter Detailed Comments, Attach 2 photos
3	Field Conditions have changed, and needs to be complete within 12 months	Update	Select Condition needs to be addressed within 12 months <ol style="list-style-type: none"> 1. Update Pending LC: <ol style="list-style-type: none"> a) Select a recommended due date, Enter Detailed Comments, Attach 2 photos
4	Field Conditions have not changed, and needs to be complete within 60 months Only for F-R Priority FDA	Update	<ol style="list-style-type: none"> 1. Select Condition needs to be addressed within 60 months 2. Update Pending LC: <ol style="list-style-type: none"> a) Select a recommended due date, Enter Detailed Comments, Attach 2 photos

Field Safety Reassessments

	Field Condition	EC Process	Actions
5	LC is a Duplicate	Cancel	<ol style="list-style-type: none"> 1. Select Cancel – Duplicate 2. Update Pending LC: <ol style="list-style-type: none"> a) Enter Detailed Comments, Attach 2 photos
6	LC is Not Valid	Cancel	<ol style="list-style-type: none"> 1. Select Cancel – Not Valid 2. Update Pending LC: <ol style="list-style-type: none"> a) Enter Detailed Comments, Attach 2 photos
7	All Work Found Completed	Cancel	<ol style="list-style-type: none"> 1. Select Cancel – All work found completed on arrival (NCOA) 2. Update Pending LC: <ol style="list-style-type: none"> a) Enter Detailed Comments, Attach 2 photos
8	Unable to access (CGI)	No Access	<ol style="list-style-type: none"> 1. Select CGI 2. Update Pending LC: <ol style="list-style-type: none"> a) Enter Detailed Comments, Attach 2 photos



Minor Work

Minor Work

Minor Work Guidance

- **Definition:** Work that can be safely accomplished by an Inspector during a detailed inspection.
- ET Contract Inspector requirements for minor work changes year after year.

Minor Work

Did you perform Minor Work at this location?

Yes

No



QC Results & Ignition Risks

2022 QC Results

Ignition Risk Attributes (IRA)

Detailed ground and climbing inspections look for conditions related to assets, that if left uncorrected, could lead to fire ignitions. In collaborating with PG&E lines of business, System Inspections have developed a set of attribute conditions that are essential in preventing ignition risks throughout our system.

It is important that you understand these risks while documenting abnormal conditions in both the Steel and Non-Steel checklists. Follow these simple reminders:

- ✓ Prioritize quality by identifying all ignition risks and ensuring accuracy for all items on the checklists. Productivity targets should never drive shortcuts in how you perform and record your inspection. Safety and Quality are key!
- ✓ When conducting a 360-degree visual inspection, make sure to focus on these targets and take quality photos with your external camera. The iPad camera is not sufficient in capturing conditions on these specific components.
- ✓ In the Inspect App summary page, make sure to review all ignition risk attributes and ensure that you have documented all identified violations. This is the final page before submitting the checklist and any associated LC's.

Ignition Risk Attributes (IRA)

Most Common Findings

Splices within 10 feet to clamp?
Guy is loose / slack?
Anchor/Guy covered by vegetation?
Cotter key missing / out of place / improperly positioned?
Conductor damaged (gunshot, broken strands, arcing, twisted bundle, bird caging) or in poor condition?
Structure has bird, animal, or insect damage?
Grading / Corona Rings in poor condition or missing?
Insulators are damaged, contaminated, arcing/tracking, or in poor condition?
Switch has visible signs of rust, corrosion, cracking, arcing, open/unlocked, tracking, contamination, damaged components?
Guy hardware bonding is installed incorrectly, damaged, or missing?
Hot-End hardware in poor condition?
Structure has breaks / cracks / splits?
Insulators are out-of-plumb (> 2 bells out-of-plumb or > 6 inches for post)?

Foundation is Earth-Covered or buried?
Pole-Top has damage or split top?
Anchor(s) damaged, cracked, corroded, rotted, or in poor condition?
Mastic sealant in poor condition?
Guy anchor head buried?
Earth around anchors eroded, soil movement, slide?
Clamps in poor condition?
Shield Wire / OPGW plate in poor condition?
Turnbuckle(s) bottomed out / out of thread / pinged?
Anchor head is buried?
Cold-End hardware is in poor condition?
Guy insulator (fiberglass or porcelain) in poor condition or missing?
Dampers missing or in poor condition (fatigued, drooping, missing weight)?
Ground wire in poor condition?
Bonding broken / missing?

Ignition Risk Rankings – Time Dependent

There are **nine** specific conditions that require a 90-day corrective action/remediation. When identifying these conditions, you must ensure the notification adheres to this time frame.

1. Hot splice greater than 100-degree differential*
2. Foundation cracks to the stub
3. Heavy guano contamination
4. Hangar plates/hardware 30–50 % material loss
5. Structure issues with main structural support damage compromising structural integrity
6. H-frame cross brace broken or missing
7. Structure out of plumb more than 3 feet and causing insulators and conductors to be compromised
8. Twisted bundled conductors
9. Stack or over tension load bearing guys

** Not expected to be found during ground inspections but may be found during other inspections.*

Quality Verification Team

QVT Findings

QVT Findings - Overview

Background

- In early 2022, Quality Verification Team (QVT) was asked by the VP of Safety & Risk to perform a monthly rolling audit of System Inspections for the duration of the 2022 enhanced overhead inspection cycle.
 - Audit began 03/08/22, audited last field location on 09/28/22

Purpose of Assignment

- Audit field inspections completed by Compliance Inspectors
 - All inspections must be completed in accordance with the ETPM Manual and the Inspection Job Aids

Scope

- The scope of this audit includes documentation and work execution of:
 - Overhead (OH) inspections in HFTD areas
 - Focus on Critical Attribute list from SI QC

QVT Findings - Overview

Methodology

Reviewed approximately 2,696 assets, system wide

- Audit to a 99% confidence level
- Locations were randomized
- Sampling Source: ET Attainment Report
- Audits were conducted monthly via previous month's completed inspection data


Tools & References

- ETPM Manual and TIL Documents
- Overhead Inspection Job Aids and Guidance Documents
- Quality Verification processes
- Enterprise Corrective Action Program (ECAP)

Frequent Findings


Top 5 Critical Findings:

- Guy is loose or slack
- Guy hardware bonding is installed incorrectly, damaged or missing
- Pole-top has damage or split top
- Structure has bird, animal or insect damage
- Grading/Corona rings in poor condition or missing



Top 5 Non-Critical Findings:

- High signs missing or installed incorrectly
- Climbing steps installed incorrectly
- Fencing issues
- Missing tower number
- Guy insulator not attached directly at wood pole




Top Critical Finding

Comments

- Slack guy wire
- Structure # - 003/047
- SAP # - 40814811

Reference

- TD-1001M – JA13



2nd Most Frequent Critical Finding

Comments

- Only one bolt is bonded
- Structure # - 013/011
- SAP # - 40601872

Reference

- TD-1001M – JA13



3rd Most Frequent Critical Finding

Comments

- Substantial split at the crossarm (pole top)
- Structure # - 007/143
- SAP # - 40907478

Reference

- TD-1001M – JA06



2022 QC Results

Steven Ruiz (SDRe)

Electric Quality Control Specialist



Smart Mobile Workforce (SMW) Application

SMW App

- This app allows access to documents offline:
 - Guidance documents and job aids
 - Key Contacts List
 - Other important documents



SMW App

View and search for guidance documents and job aids:




1. Tap SMW 7.2 App icon



2. Tap Mobile Library icon





3. Tap System Inspections to view work docs



SMW App Library


- View and search for guidance documents and job aids :
 - View docs in folders and subfolders
 - Scroll down to view more
 - Type document name to search for docs in search field



SMW App Search

View and search for documents:

1. Enter the document name in search bar
2. Tap Search
3. Search results displays the document
 - Tap the document
 - Tap Open Online or download to your device and view





Demo SMW App


Help Desk



Helpdesk is here for you!

Issue Tracker App

- Field Inspectors will report Issues to the System Inspection (SI) Help Desk team using the **Issue Tracker app**.
- The Helpdesk team will respond with an answer to their questions quickly.



Help Desk Supported Activities

Hours of Operations: Monday – Friday: 7am to 3pm (0700-1500)

Reach us using the following:

- Using the Issue Tracker App (Creating a ticket)
- Through Email: SIHelpDesk@PGE.onmicrosoft.com
- Calling and leaving a Voicemail: **925-328-5510**


SI HelpDesk Applications supported:

- Enterprise Alerts
- Maps+ Field Intel
- Inspect ED/ET Navigation
- Inspect ED/ET Checklist Navigation
- Inspect ED/ET/Engage Checklist MPs
- App Crashes, Photos/Stuck Synch Issues
- App Version/updates, App/Maps/MP not Loading
- Other – Electronic Access, Enhancement Request, Engage, IOS Updates, FSR

Applications NOT supported by Helpdesk:

- All Halo Issues supported by Planners
- Locked Passwords supported by TSC
- Lost/Stolen iPads supported by Corp Security to wipe iPad and to contractor's agency for BYOD
- CGI Customer supported by Customer Line
- Hostile Customer supported by Corp Security Level 1

SI Help Desk Process



Issue Tracker App Overview



Issue Tracker

1:31 PM Thu Nov 4

Issue Tracker App - UAT

78%

Post A New Issue

* Issue Description

2-Tap the description field

* Priority

* Line of Business

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Find Items

* Supervisor

Find items

* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

Attach file

Submit

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar


Training

More



Logging an Issue

Issue Tracker



Issue Tracker


1:31 PM Thu Nov 4

Issue Tracker App - UAT


78%

<

...



Post A New Issue



* Issue Description

* Priority

* Line of Business

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Find Items

* Supervisor

Find items


* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

 Attach file

Submit

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training

More

2-Tap the **description** field

1:33 PM Thu Nov 4


Issue Tracker App - UAT

78%


<

3-Enter a detailed description

...



Post A New Issue



* Issue Description

Add detailed description

* Priority

* Line of Business

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Find Items

* Supervisor

Find items


* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

 Attach file

Submit

 Activity

 Chat

 Teams

 Tasks by Planner and To Do

 Calendar

 Training



...

More

Issue Tracker

1:33 PM Thu Nov 4
78%

<
Issue Tracker App - UAT
...


Post A New Issue


* Issue Description

Add detailed description

* Priority

4-Tap Priority

* Line of Business

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Find Items

* Supervisor

Find items


* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

 Attach file



Submit

Activity
Chat
Teams
Tasks by Planner and To Do
Calendar
Training
More

Issue Tracker

10:06 AM Fri Oct 1 78%


< Issue Tracker App - UAT ...

 Find items 

* Issue Description
Add detailed description

* Submitter
S3L1@pge.com

* Contact Number

Attachments
There is nothing attached.
 Attach file

of Business
items
rvisor
items
Category
items

5-Select the Priority. Tap **Not-urgent**


Not-urgent
Need a response today
Need a response now

Activity Chat Teams Tasks by Planner and To Do Calendar Training More


1:35 PM Thu Nov 4

Issue Tracker App - UAT

6-Tap Line of Business



Post A New Issue



* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Find Items

* Supervisor

Find items


* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

 Attach file

Submit

 Activity

 Chat

 Teams

 Tasks by Planner and To Do

 Calendar


 Training

 More


Issue Tracker

1:35 PM Thu Nov 4

Issue Tracker App - UAT

7% 

< ...



* Issue Description

Add detailed description


* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

Attachments

There is nothing attached.

 Attach file

Transmission

Distribution

of Business

ervisor

Items

Category

7-Select Distribution

Activity Chat Teams Tasks by Planner and To Do Calendar Training More

Issue Tracker

1:36 PM Thu Nov 4

Issue Tracker App - UAT

...

Post A New Issue

* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

Distribution

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Find Items

* Supervisor

Find items

* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

Attach file

Submit

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training

More

8-Tap Inspector

Issue Tracker

1:46 PM Thu Nov 4

Issue Tracker App - UAT

76%

Find Items

* Issue Description

Add detailed description

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

Attachments

There is nothing attached.

Attach file

Albrigo, Ted (TRA1@pge.com)

Alma, Jacinta (J1Db@pge.com)

ALLURI, RAJESH (R6AX@pge.com)

Amo, Ian (IJA1@pge.com)

Amuluru, Jyothi (N1AC@pge.com)

Anderson, Jack (RJAe@pge.com)

Audelo, Joseph (JSA5@pge.com)

Bateman, Matthew (MNB4@pge.com)

Bates, Dawn (D0BS@pge.com)

Bautista, Karl (K5B5@pge.com)

Bilbo, Thomas (TDB0@pge.com)

Bockrath, Michael (M2Bo@pge.com)

Bowman, Bobby (BLBI@pge.com)

of Business

tribution

ervisor

items

Category

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training

More

9-Tap Find Items

1:37 PM Thu Nov 4

Issue Tracker App - UAT

Find Items

10-Enter LANID

* Issue Description

Add detailed description

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

Albrigo, Ted (TRA1@pge.com)

Alma, Jacinta (J1Db@pge.com)

ALLURI, RAJESH (R6AX@pge.com)

Amo, Ian (IJA1@pge.com)

Amuluru, Jyothi (N1AC@pge.com)

Anderson, Jack (RIAe@pge.com)

Q W E R T Y U I O P

A S D F G H J K L return


↑ % - + = / ; : ! ? ↑

.?123 .?123

Issue Tracker

1:49 PM Thu Nov 4 76%

Issue Tracker App - UAT



S3L1

Lorain, Steven (S3L1@pge.com)

* Issue Description

Add detailed description

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

of Business

tribution

ervisor

items

Category

"S3L1"

q w e r t y u i o p [backspace]

@ # \$ % & * () ' " [return]

[home] z x c v b n m , . ; : [up]

[numbers] [emoji] [microphone] [spacebar] [numbers] [keyboard icon]

11-Tap Inspector

S3L1


Lorain, Steven (S3L1@pge.com)

Steven Lorain (S3L1@pge.com)


1:50 PM Thu Nov 4

Issue Tracker App - UAT

...



Post A New Issue



* Issue Description

Add detailed description

* Priority

Not-urgent

▼

* Line of Business

Distribution

▼

* Submitter

Steven Lorain (S3L1@pge.com)

▼

* Inspector

Lorain, Steven (S3L1@pge.com)

▼

* Supervisor

Find items

▼

* Contact Number

* Primary Category


▼

* Sub Category

▼

Attachments

There is nothing attached.

 Attach file

Submit

12-Tap Supervisor

 Activity

 Chat

 Teams

 Tasks by Planner and To Do

 Calendar


 Training

 More

Issue Tracker

2:39 PM Thu Nov 4 73%

Issue Tracker App - UAT



* Issue Description

Add detailed description

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

Td

Bilbo, Thomas (TDB0@pge.com)

of Business

tribution

rvisor

Category

13-Enter LANID and Select Supervisor

“Td” Ted Test

1 2 3 4 5 6 7 8 9 0

q w e r t y u i o p

@ # \$ % & * () ' " return

a s d f g h j k l

↑ % - + = / ; : ! , ?

z x c v b n m , .

↑ ↓



↑ ↓

↑ ↓

Issue Tracker

2:41 PM Thu Nov 4
73%

<
Issue Tracker App - UAT
...


Post A New Issue


* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

Distribution

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Lorain, Steven (S3L1@pge.com)

* Supervisor

Bilbo, Thomas (TDB0@pge.com)


* Contact Number

* Primary Category

* Sub Category

Attachments

There is nothing attached.

 Attach file

14-Tap Contact Number


Submit

Activity
Chat
Teams
Tasks by Planner and To Do
Calendar
Training
More


2:45 PM Thu Nov 4

Issue Tracker App - UAT

73%



Post A New Issue



* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

Distribution

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Lorain, Thomas (TDB0@pge.com)

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Contact Number

5557771212

* Primary Category

Other

* Sub Category

Other

15-Enter Contact Number

16-Tap Keyboard Key to close

1

2

3

4

5

6

7

8

9

0

@

#

\$

&

*

(

)

'

"

#+=

%

-

+

=

/

<

>

!

?


undo

ABC


16-Tap Keyboard Key to close

2:48 PM Thu Nov 4

Issue Tracker App - UAT



Post A New Issue



* Issue Description

Add detailed description

* Submitter


Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

There is nothing attached.

 Attach file

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

* Line of Business

Distribution

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Sub Category

Submit

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training


More

17-Tap Primary Category

2:51 PM Thu Nov 4

Issue Tracker App - UAT

72%



* Issue Description

Add detailed description

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

There is nothing attached.

Attach file

Data/Reporting

Technology

Training/Process/Access

Unknown

18-Select the best Primary Category

of Business

tribution

ervisor

, Thomas (TDB0@pge.com)

Category

Activity

Chat

Teams

Tasks by Planner and To Do


Calendar

Training


More

2:52 PM Thu Nov 4

Issue Tracker App - UAT



Post A New Issue



* Issue Description

Add detailed description

* Submitter


Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

There is nothing attached.

 Attach file

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

Technology

* Line of Business


Distribution


* Supervisor


Bilbo, Thomas (TDB0@pge.com)


* Sub Category


Submit


 Activity


 Chat

 Teams

 Tasks by Planner and To Do

 Calendar

 Training


 More

19-Select Sub Category

Issue Tracker

2:54 PM Thu Nov 4 71%

Issue Tracker App - UAT



* Issue Description

Add detailed description

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

There is nothing attached.

Attach file

App Crashing

App Not Loading/Slow

Enhancement Request

Maps Not Downloading

Other

Photos Synching/ Stuck

Unable To Sync Work Orders

of Business

tribution

rvisor

p, Thomas (TDB0@pge.com)

Category


20-Select the best Sub Category

Activity Chat Teams Tasks by Planner and To Do Calendar Training More


2:55 PM Thu Nov 4

Issue Tracker App - UAT

71%



Post A New Issue



* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

Distribution

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Lorain, Steven (S3L1@pge.com)

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Contact Number

5557771212

* Primary Category


Technology

* Sub Category

App Not Loading/Slow

Attachments

There is nothing attached.

 Attach file

Submit

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training

More

21-Add your attachments.
Tap **Attach File**

Issue Tracker

2:58 PM Thu Nov 4

Issue Tracker App - UAT

...

Post A New Issue

* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

Distribution

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Lorain, Steven (S3L1@pge.com)

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Contact Number

5557771212

* Primary Category

Technology

* Sub Category

App Not Loading/Slow

Attachments

There is nothing attached.

Attach file

Photo Library

Take Photo or Video

Browse

Submit

Note: Use this section to attach a file from the Photo Library, Take a Photo and attach it, or browse for a file(s) to attach.

22-Tap Photo Library, Take Photo or Video, or Browse

Activity

Chat

Teams

Tasks by Planner and To Do


Calendar

Training


More

2:58 PM Thu Nov 4

Issue Tracker App - UAT



Post A New Issue



* Issue Description

Add detailed description

* Priority

Not-urgent

* Line of Business

Distribution

* Submitter

Steven Lorain (S3L1@pge.com)

* Inspector

Lorain, Steven (S3L1@pge.com)

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Contact Number

5557771212

* Primary Category

Technology

* Sub Category

App Not Loading/Slow

Attachments

There is nothing attached.

Attach file

Photo Library

Take Photo or Video

Browse

Submit

Activity

Chat

Teams


Tasks by Planner and To Do

Calendar

Training

More

23-Tap Photo Library



9:37 AM Fri Nov 5

Issue Tracker App - UAT

65%

Post A New Issue

* Issue Description

Add detailed comments

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

544F1071-FAEF-48DA-9ED0-1...

Un..

X

Attach file

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

Technology

* Line of Business

Distribution

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Sub Category

App Not Loading/Slow

Submit

26-Tap Attach file

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training

More

226

9:43 AM Fri Nov 5

In progress: Open Positions
Want to join on this device?


Join

×


<

Issue Tracker App - UAT

...



Post A New Issue



* Issue Description

Add detailed comments


* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

 4B52DAB7-EA7A-4E13-ADAD-1... Un..

Attach file

Photo Library

Take Photo or Video

Browse

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

Technology

* Line of Business

Distribution

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Sub Category

App Not Loading/Slow

Submit

27-Tap Take a Photo or Video

Activity

Chat

Teams


Tasks by Planner and To Do

Calendar

Training

More

Issue Tracker



9:48 AM Fri Nov 5

Issue Tracker App - UAT

65%

Post A New Issue

* Issue Description

Add detailed comments

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

4B52DAB7-EA7A-4E13-ADAD-1...

Un..

×

image.jpg

Unsaved

×

Attach file

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

Technology

* Line of Business

Distribution

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Sub Category

App Not Loading/Slow

Submit

29-Tap Attach file

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training

More

229

9:51 AM Fri Nov 5

Issue Tracker App - UAT

65%

Post A New Issue

* Issue Description

Add detailed comments

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

4B52DAB7-EA7A-4E13-ADAD-1... Un..

image.jpg Unsavd

Attach file

Photo Library

Take Photo or Video

Browse

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

Technology

* Line of Business

Distribution

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Sub Category

App Not Loading/Slow

Submit

27-Tap Browse

Activity

Chat

Teams


Tasks by Planner and To Do

Calendar

Training

More

Issue Tracker



9:52 AM Fri Nov 5

Issue Tracker App - UAT

64%

Post A New Issue

* Issue Description

Add detailed comments

* Submitter

Steven Lorain (S3L1@pge.com)

* Contact Number

5557771212

Attachments

4B52DAB7-EA7A-4E13-ADAD-1... Un.. X

image.jpg Unsaved X

Screenshot 2021-11-05 at 9.1... Uns.. X

Attach file

* Priority

Not-urgent

* Inspector

Lorain, Steven (S3L1@pge.com)

* Primary Category

Technology

* Line of Business

Distribution

* Supervisor

Bilbo, Thomas (TDB0@pge.com)

* Sub Category

App Not Loading/Slow

Submit

31-When done, tap Submit

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar


Training

More



Viewing My Issues

Issue Tracker



Issue Tracker

9:57 AM
Fri Oct 1

Issue Tracker App - UAT

My Issues

Assigned To: [NA](#)
Priority: [Not-urgent](#)
Line Of Business: [Both](#)
Issue Description: [Condition issue](#)
ID: [55](#)

New

Assigned To: [NA](#)
Priority: [Need a response now](#)
Line Of Business: [Distribution](#)
Issue Description: [add](#)
ID: [54](#)

New

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training


More

2-Enter the description you want to search

04

All Issues List

Issue Tracker



9:58 AM Fri Oct 1

Issue Tracker App - UAT

79%

2-Enter the description you want to search

All Issues

Issue Description

Priority

Line Of Business

Issue Description

Priority

Line Of Business

Assigned To: NA

Priority: Not-urgent

Line Of Business: Both

Issue Description: Condition issue

ID: 55

Assigned To: NA

Priority: Not-urgent

Line Of Business: Both

Issue Description: add

ID: 54

Assigned To: NA

Priority: Not-urgent

Line Of Business: abc

Issue Description: Test Both chat

ID: 53

Assigned To: NA

Priority: Not-urgent

Line Of Business: Distribution

Issue Description: Test ED

ID: 52

Assigned To: NA

Priority: Not-urgent

Line Of Business: Transmission

Issue Description: Test ET chat

ID: 51

Assigned To: NA

Priority: Not-urgent

Line Of Business: Distribution

Issue Description: Test ED

ID: 50

Activity

Chat

Teams

Tasks by Planner and To Do

Calendar

Training











More




Inspect App Navigation

Maps + Color Legend


Maps+ Color Legend

-  Urban Area
-  Beach/Dune/Sand Area
-  Ocean/Body of Water
-  Park/Garden/Golf Course
-  Woodland
-  School/University/Shopping Center/Hospital/Amusement Park/
Industrial Area/Amusement Park
-  Military Area
-  Airport
-  Tier 3 Fire Threat District
-  Tier 2 Fire Threat District




Navigation

1. Menu
2. Search
3. Map preferences
4. Current location bullseye
5. Map viewing scale
6. Map updated date




Menu Options

1. Refresh Map
2. Replace Map
3. Give Feedback
4. Daily Activity Log
5. Tailboards
6. Your Role
7. Main Work Center
8. App Version Number
9. Log Out



Search


1. Address, Cross Street, Coordinate
2. TLine by Name
3. **SAP Equipment ID**
4. Pole Number
5. Underground Structure
6. Field Switch
7. Substation Name



The screenshot shows a search modal window titled "Search" with a "Close" button. Inside the modal, there is a list of search criteria: "Address, Cross Street, or Coordinates", "TLine by Name", "SAP Equipment ID", "Pole or Tower Structure", "Underground Structure", "Field Switch", and "Substation Name". The "SAP Equipment ID" option is highlighted with an orange box, and an orange arrow points from the "SAP Equipment ID" item in the list on the left to this box.

Search Criteria	Options
Address, Cross Street, or Coordinates	
TLine by Name	
SAP Equipment ID	
Pole or Tower Structure	>
Underground Structure	>
Field Switch	>
Substation Name	


Map Preferences - Layers



Alerts

Scale (Zoom Levels 500 or less)


1. Locked Gates
2. Bad Dogs
3. Safety Alerts



Field Safety Alerts

Scale (Zoom Levels 2,500 or less)

Required to notify your PG&E
Lead before entering Geo-
Fenced areas



Helpful Contact Info



Issue	Role	Contact	Hours
Halo Issues	SI Planners	TransmissionAssetStrategist@pge.com	Workdays 7 AM to 4 PM
Help Desk	SI Help Desk	925-328-5510	Workdays 7 AM to 3 PM
Locked Passwords	TSC	415-973-9000 option 1	24/7
Lost/Stolen iPads <i>Remember to notify your lead/supervisor first</i>	TSC	415-973-9000 option 1	24/7
Hostile Customer Level 1	Security Control Center Emergency Services	800-691-0410 Call 911	24/7
CGI Hotline	Customer LCE	925-415-6600	Mon – Thur 7 AM to 5 PM Fri – 7 AM – 4 PM

Training Contents– Contractors

- **Training at Contract Vendor Location**

- IS Net World Training: Foundations for Contractors
- IS Net World Training: SAFE-0101 Corporate Contractor Safety Orientation
- IS Net World Training: EQIP-0200 Rural Driving Safety
- IS Net World Training: SAFE-1503 Fire Danger Precautions
- IS Net World Training: SAFE-1507 Fire Danger Precautions Supplemental
- IS Net World Training: SAFE-4513 Electric Operations Safety

- **Additional Web-Based Training courses**


- My Learning: ISEC-9022 Security & Privacy Awareness
- My Learning: CORP-9046 Records & Information Management
- My Learning: CORP-9124 Privacy Awareness
- My Learning: ELEC-0708 Oil Spill Response
- My Learning: ELEC-0417 Transmission Patrols& Inspections

- **Instructor Led Training**

- PSOS-0410 Onboarding
- PSOS-0451 Process
- PSOS-0452 Mobile

Next Steps

- Questions
- Record Attendance
- Next class starts at 7:30 AM tomorrow
- Arrive to class on time
- Topics include Mobile process
- Drive safely



Thank You