

**PACIFIC GAS AND ELECTRIC COMPANY
Wildfire Mitigation Plans
Rulemaking 18-10-007
Data Response**

PG&E Data Request No.:	TURN_017-Q01		
PG&E File Name:	WildfireMitigationPlans_DR_TURN_017-Q01		
Request Date:	February 22, 2021	Requester DR No.:	WMP 2021 DR TURN-PGE-003
Date Sent:	February 25, 2021	Requesting Party:	The Utility Reform Network
PG&E Witness:		Requester:	Marcel Hawiger

QUESTION 01

PG&E discusses the requirements of GO 95 and GO 165 in multiple places of its WMP, including the statement “To address the risk of a distribution pole failure, PG&E has an extensive condition monitoring program for wood poles in accordance with requirements of GO 165” (p. 483). Please provide all Standard Operating Procedure (SOP) documents for 2020 and 2019, separately, that governed PG&E’s operationalization of GO 95 and GO 165 for purposes of distribution overhead inspection and remediation work.

ANSWER 01

PG&E objects to the request for “all Standard Operating Procedure (SOP) documents” as overbroad and burdensome. Subject to and without waiving this objection, we are providing 3 documents that articulate our inspection program which operationalizes GO95 and GO165 for PG&E:

1. PG&E’s procedure on inspecting, reinforcing, and using wood poles – see attachment “WildfireMitigationPlans_DR_TURN_017-Q01Atch01”
2. PG&E’s job aid on overhead inspection – see attachment “WildfireMitigationPlans_DR_TURN_017-Q01Atch02”
3. PG&E’s Electric Distribution Preventive Maintenance Manual – see attachment “WildfireMitigationPlans_DR_TURN_017-Q01Atch03”